

[Next Unread Message](#)

**View Message**

**Sent on** 09 09 2019 **Expires on** 09 23 2019

**From** Parts and Service Division

**Subject** Request for Visit: 2019 Odyssey Sliding Door Inop Under Power

**PRIORITY/ACTION REQUIRED**

To: All Honda Service Managers/Advisors  
From: Technical Research & Support Group  
RE: Request for Visit: 2019 Odyssey Sliding Door Inop Under Power

This message is solely directed to Honda dealership personnel; please handle accordingly.  
Print this iN message and provide a copy to the Shop Foreman and all Service Advisors.

**Background**

American Honda Motor Co., Inc. (AHM) is investigating certain 2019 Odysseys with a customer complaint of the sliding door not opening or closing under power or reversing during opening/closing operation. To better understand the cause of this condition, AHM would like to inspect the vehicle prior to you attempting a repair of any kind.

**Qualifiers**

AHM is interested ONLY if the vehicle meets the following requirements:

1. Must be able to duplicate the issue.
2. No repair has been attempted for this issue.

**Action Required**

If you have or know of such a vehicle, please call the Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.