

Subject: Engineering Information – Driver Seat Track Will Not Adjust Forward and/or Backwards and Becomes Seized

This EI has been revised to end the need for information from the field. Please discard PIE0509A.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Enclave	2016	2019				
Cadillac	XT5	2017					
Chevrolet	Malibu	2016					
	Traverse						
GMC	Acadia						

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	3
Modified	Released February 15, 2019 May 16, 2019 – Added the Acadia, XT5, Traverse and Enclave models. August 27, 2019 – Ended the need for further information from the field.