


# Latest Vehicle Concern Fixes



<p><b>No Audio Output or Loss of Audio</b></p>	<p><b>19 – 20MY E-PACE, F-PACE, I-PACE, F-TYPE, XE, XF, XJ, Range Rover, RR Sport, RR Velar, RR Evoque, Discovery, Discovery Sport with InControl Touch Pro Audio System</b></p> 
--	---

**Customer Voice:**

- Customer states there is no audio output from the speakers on all sources

**Technical Description:**

- IMC hardware failure

**Status:**

- Primarily reported on 19MY vehicles
- LR – SSM 74491 has been released on July 26<sup>th</sup> 2019
- JAG – SSM 74490 has been released on July 26<sup>th</sup> 2019
- Part stock has been confirmed clean.

