

# Technical Service Bulletin

<b>Topic</b>	New Continental GT - Spurious Mood lighting DTC's
<b>Market area</b>	Bentley: worldwide (2WBE),Hongkong-Macau (5HK)
<b>Brand</b>	Bentley
<b>Transaction No.</b>	2052496/2
<b>Level</b>	EH
<b>Status</b>	Released for publishing
<b>Release date</b>	Aug 21, 2019

## New customer code

Object of complaint	Complaint type	Position
vehicle service -> vehicle diagnosis -> Guided Fault Finding (GFF)	control modules, services -> with fault stored in the DTC memory	
lighting, signaling -> interior lighting -> ambient lighting	functionality -> irregular	

## Vehicle data

### New Continental GT

#### Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
3S3*	2018	E		*	*	*
3S3*	2019	E		*	*	*
3S3*	2020	E		*	*	*

#### PR numbers

<b>PR numbers</b>
?:with PIL

## Documents

<b>Document name</b>
<a href="#">master.xml</a>

## Condition

### Workshop findings:

Upon interrogation of the vehicle fault memory spurious DTC's can be logged in **09 – Central Electrics** relating to the *Mood lighting* system

The lamp is fully functional and there is no customer complaint

## Technical Background

The DTC's are currently under investigation within the factory

## Production Solution

\*

## Service

If the illumination is operating correctly and there is no customer complaint then the code can be ignored as it has no effect on the function of the lamp

**Do not replace the lamp if it is functioning correctly**

**A groundless parts replacement under warranty will be debited**