

Technical Service Bulletin

Topic	Daytime running light/s not working - Warning message within the DIP
Market area	Bentley: worldwide (2WBE),Hongkong-Macau (5HK)
Brand	Bentley
Transaction No.	2055589/1
Level	EH
Status	Released for publishing
Release date	Aug 21, 2019

Diagnostic trouble codes

Diagnostic address	Diagnostic trouble code	Fault symptom	Storage state
0029 - Light Control Left	C10EF04: Signature light bulb Faulty		Intermittent
0029 - Light Control Left	C10EF04: Signature light bulb Faulty		static
0039 - Light Control Right	C10EF04: Signature light bulb Faulty		Intermittent
0039 - Light Control Right	C10EF04: Signature light bulb Faulty		static

New customer code

Object of complaint	Complaint type	Position
lighting, signaling -> exterior lighting -> daytime running light	functionality -> partially out of order	left
lighting, signaling -> exterior lighting -> daytime running light	functionality -> partially out of order	right

Vehicle data

New Continental GT and New Continental GTC

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
3S3*	2018	E		*	*	*
3S3*	2019	E		*	*	*
3S3*	2020	E		*	*	*
3S4*	2019	E		*	*	*
3S4*	2020	E		*	*	*

Chassis numbers

Manufacturer	Filler	Type	Filler	MY	Factory	From	To	Prod from	Prod to
SCB	*	*	*	*	C	000001	075398		

Documents

Document name
master.xml

■

Condition

Customer statement

- Left and/or right daytime running light/s not working (Figure 1)



Figure 1

- Warning message also evident within the DIP (Figure 2)



Figure 2

Workshop Findings

- DTC C10EF04 evident within Diagnostic address 29 Light control left and/or 39 Light control right

Technical Background

Refer to Measure section

Production Solution

All VIN's from SCBCG2ZG7LC075398 are not affected

Service

1) Using ODIS clear DTC C10EF04

- Switch the ignition OFF and back ON again
- Check and confirm DTC C10EF04 has been successfully cleared
- Check the operation of the daytime running lamps
- Should the daytime running lamps now be working to specification and the DTC has cleared, no further diagnosis is required

NOTE: Should the daytime running light/s still not be working and/or the DTC is evident please raise a DISS query ensuring the latest available diagnostic log and clear photographs are attached then await feedback prior to carrying out any further repairs