

CVT Fill Plug Pops Out or Leaks?

AFFECTED VEHICLES

Year	Model	Trim
2016-18	Civic	ALL with CVT
2015-18	Fit	ALL with CVT
2016-18	HR-V	ALL with CVT

Have you noticed the fill plug on a CVT has popped out or seems to be leaking? This is caused by pressure building up at the fill plug due to the vent cap getting plugged with debris.



To fix the issue, simply remove the vent cap, clean it out with compressed air, and install with the arrow in the same direction. Then, replace the fill plug if it fits loose or has popped off and, if needed, top off the CVT with Honda Genuine HCF-2 Transmission Fluid (P/N 08200-HCF2)