



**** SOLUTION ****

Title Mack Chassis - Floor mounted Dimmer Switch: Installation Instructions For New Part


Mack Models

Mack Model Legacy

**** SOLUTION ****

Cause Dimmer switch part number 1502-7762 is no longer available. A new design is available for replacements.

Solution Headlight dimmer switch part number 1502-7762 is no longer available. The replacement is PN 1502-7784 (**pictured below**). The new switch will come with a different connector. The technician will need to cut the wires to a desired length and use recommend butt splice connectors in order to install new switch on older applications.



Floor Mounted Dimmer Switch p/n 1502-7784

Solution visibility Dealer distribution

Function(s)/component(s) affected

Function affected Connector , wiring harness

Function Group

Function Group 35 lighting

Administration

Author A241298

Dealer ID A241298

Last modified by A241298

Creation date 24-07-2019 20:07

Date of last update 14-08-2019 14:08

Status Published
