

SS: 1034471 TBB Rear LED Markers Lights stays illuminate

This Service Solution does not imply any special warranty coverage. Standard warranty guidelines and coverage apply. This Service Solution is provided to assist Dealers/Customers in resolving the issue when the brakes are applied, the rear side led marker lights illuminate.

Applicable Vehicles

EFX / HDX

Symptoms

LED Rear marker lights illuminate

Issue

Battery Draw

Solution:

Adding a Diode in the Marker light circuit the Brown wire, Diode toward the Light

SS: 1034471 TBB Rear LED Markers Lights stays illuminate

