



Technical Service Bulletin

91 Rearview camera intermittently inoperative, DTC 02203 is stored in the rearview camera control module

91 19 92 2041430/6 September 27, 2019. Supersedes Technical Service Bulletin Group 91 number 18-70 dated February 1, 2018 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q3	2015 - 2018	All	With rearview camera
A6, A7	2014 - 2015	All	With rearview camera
A4, A5, A5 Cabriolet, and Q5	2013 - 2016	All	With rearview camera

Condition

REVISION HISTORY		
Revision	Date	Purpose
6	-	Revised title Revised header (Added model years)
5	02/01/2019	Revised header (Removed A8 and Q7)
4	01/11/2017	Revised header (Added PR code)

Customer states:

- The rearview camera image is not displayed on the MMI display.

Workshop findings:

The following DTC is logged in the rearview camera system control module, J772 (address word 006C):

- DTC 02203** (audio/video input 1) with one of the following fault symptoms:
 - 11 open circuit.
 - 8 implausible signal.

Technical Background

An issue with the wiring harness may cause the condition.



Technical Service Bulletin

Production Solution

Not applicable.

Service

1. Before proceeding, confirm that the DTC and one of the fault symptoms listed in the *Condition* are logged in the rearview camera system control module, J772 (address word 006C). If the DTC is not listed with one of the fault symptoms, this bulletin does not apply.
2. Check the wiring of the R189 reverse camera at connector T2az and T1y (Figure 1). Repair any loose connectors or pins, corrosion, or any other physical damage.




Figure 1. Check the wiring of the R189 reverse camera at connector T2az and T1y.



Technical Service Bulletin

If no problems are found with the wiring or connections of the rearview camera, continue to step 3 to replace the rearview camera harness (Figure 2).




Figure 2. Reverse camera harness to be replaced.

3. Remove the original reverse camera from the vehicle. Follow applicable steps in the Elsa repair manual for the specific vehicle.



Technical Service Bulletin

4. Remove the original harness from the reverse camera (Figure 3):

- First, locate the locking tab on the reverse camera harness.
- Next, using a small flat head screwdriver, lift up on the locking tab.
- Finally, snap the old locking tab off the defective harness to prevent reuse.




Figure 3. Locate locking tab (1), lift up on the tab with a screwdriver (2), snap tab off (3).



Technical Service Bulletin

5. Carefully install the new reverse camera harness onto the camera assembly, as the harness can only be installed one way. The connector is keyed on both the camera and the electrical harness to prevent incorrect installation. Ensure they are correctly aligned during installation (Figure 4).




Figure 4. When installing the new reverse camera harness onto the camera assembly, ensure that the connectors are correctly aligned.

6. When the harness is fully secured to the camera, there will be an audible click sound. The sound is caused when the locking tab falls into place.
7. Reinstall the completed reverse camera assembly, following instructions as outlined in the Elsa repair manual for the specific vehicle (Figure 5).



Figure 5. Completed reverse camera assembly with a new electrical harness.



Technical Service Bulletin

Warranty

Claim Type:	<ul style="list-style-type: none"> • 110 up to 48 Months/50,000 Miles. • G10 for CPO Covered Vehicles – Verify Owner. • If the vehicle is outside any warranty, this Technical Service Bulletin is informational only. 		
Service Number:	9143		
Damage Code:	0040		
Labor Operations:	All vehicles:		
	Central wiring harness repair	9709 41XX	See SRT
	A4 and A5:		
	Rear trunk lid trim remove + reinstall	7087 1900	See SRT
	Back-up camera remove + reinstall	9143 1950	See SRT
	Back-up camera adjust	9143 1550	See SRT
	allroad:		
	Tailgate trim panel remove + reinstall	7092 1900	See SRT
	Back-up camera remove + reinstall	9143 1951	See SRT
	Back-up camera adjust	9143 1550	See SRT
	A5 Cabriolet:		
	Rear trunk lid trim remove + reinstall	7087 1900	See SRT
	Back-up camera remove + reinstall	9143 1950	See SRT
	Back-up camera adjust	9143 1550	See SRT
	A6:		
	Rear trunk lid trim remove + reinstall	7087 1900	See SRT
	Back-up camera remove + reinstall	9143 1950	See SRT
	Back-up camera adjust	9143 1550	See SRT
	A7:		



Technical Service Bulletin

	Back-up camera remove + reinstall	9143 1900	See SRT
	Back-up camera adjust	9143 1550	See SRT
	Q3:		
	Tailgate trim panel remove + reinstall	7092 1900	See SRT
	Back-up camera remove + reinstall	9143 1950	See SRT
	Back-up camera adjust	9143 1550	See SRT
	Q5:		
	Tailgate trim panel remove + reinstall	7092 1900	See SRT
	Back-up camera remove + reinstall	9143 1950	See SRT
	Back-up camera adjust	9143 1550	See SRT
Diagnostic Time:	GFF	0150 0000	Time stated on the diagnostic protocol (Max 100 TU)
	Road test prior to service procedure	No allowance	0 TU
	Road test after service procedure	No allowance	0 TU
Claim Comment:	As per TSB #2041430/6		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Always check with your Parts Department and/or ETKA for the latest information and parts bulletins.		
Part Number	Part Description	Quantity
8K0971086D	Harness	01
See ETKA	Fasteners, Bolts, Nuts, and Screws as needed per the Repair Manual	See ETKA/ELSA



Technical Service Bulletin

Additional Information

All parts and service references provided in this TSB (2041430) are subject to change and/or removal.

©2019 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.