



Technical Service Bulletin

42 Stabilizer bar - coupling link

42 19 40 2056387/1 October 7, 2019.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q3	2019	000001 - 081533	Not Applicable

Condition

Customer states:

- Noises from the rear suspension at low speeds.

Workshop findings:

- Noise is coming from the rear stabilizer coupling rod (left and/or right side).

Technical Background

Not applicable.

Production Solution


Not applicable.

Service

Replace the affected coupling rod as described in Elsa at, *Repair Manual >> Chassis >> Suspension, Wheels, Steering >> 42 Rear Suspension >> Stabilizer Bar >> Coupling Rod, Removing and Installing.*

Warranty

Claim Type:	<ul style="list-style-type: none">110 up to 48 Months/50,000 Miles.G10 for CPO Covered Vehicles – Verify Owner.If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.
Service Number:	4291



Technical Service Bulletin

Damage Code:	0010		
Labor Operations:	Anti-Roll Bar Coupling Link remove + reinstall	4291 1900	See SRT
	Wheel remove + reinstall	4405 1900	See SRT
Diagnostic Time:	Not applicable	No allowance	0 TU
	Road test prior to the service procedure	0121 0002	10 TU
	Road test after the service procedure	0121 0004	10 TU
Claim Comment:	As per TSB #2056387/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Always check with your Parts Department and/or ETKA for the latest information and parts bulletins.		
Part Number	Part Description	Quantity
See ETKA	Fasteners, Bolts, Nuts, and Screws as needed per the Repair Manual	See ETKA/ELSA
See ETKA	Coupling link	01 or 02

Additional Information

All part and service references provided in this TSB (2056387) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2019 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.