



Preliminary Information

PIT5710 A/C Inoperative, Blows Warm or Poor Performance Due to Low Refrigerant Charge, Refrigerant Leak

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Enclave	2018 - 2020	All	All	All	All
Chevrolet	Traverse	2018 - 2020	All	All	All	All

Involved Region or Country	North America
Condition	Some customers may comment that the A/C is blowing warm, is exhibiting poor performance or of a general lack of air conditioning, or the technician may find low or empty refrigerant in the system.
Cause	If a leak cannot be found on any external components, the Auxiliary Air Conditioning Evaporator may be leaking.

Correction:

Inspect the Auxiliary Air Conditioning Evaporator for leaks.

Warranty Information

The correction for this concern may be one of several repairs described above. For vehicles repaired under warranty, please use the appropriate warranty labor operation based on the actual cause and repair.

Version History

Version	1
Modified	09/19/2019 - Created on.



GENERAL MOTORS