

# Latest Vehicle Concern Fixes



<b>No Audio Output or Loss of Audio</b>	19 – 20MY E-PACE, F-PACE, I-PACE, F-TYPE, XE, XF, XJ, Range Rover, RR Sport, RR Velar, RR Evoque, Discovery, Discovery Sport with InControl Touch Pro Audio System
<p><b><u>Customer Voice:</u></b></p> <ul style="list-style-type: none"><li>• Customer states there is no audio output from the speakers on all sources</li></ul> <p><b><u>Technical Description:</u></b></p> <ul style="list-style-type: none"><li>• IMC hardware failure</li></ul> <p><b><u>Status:</u></b></p> <ul style="list-style-type: none"><li>• Utilize Pathfinder Guided Diagnostic flow to assist in diagnosing audio concerns</li><li>• LR – SSM 74491 has been released on July 26<sup>th</sup> 2019</li><li>• JAG – SSM 74490 has been released on July 26<sup>th</sup> 2019</li><li>• Part stock has been confirmed clean.</li></ul>	

