

9003968

08/28/2019

MY11-19 DS MY11-13 DJ MY12-19 DX MY12-13 DD

MY13 D2 MY14-18 KL MY15-17UF MY19 DT

GPOP - Issue Review System

Part Number: 52014588A\$, 52014609A\$, 52014619A\$, 52014620A\$, 52014753A\$, 52014798A\$, 52014808A\$, 55057062A\$, 68197293A\$, 68229581A\$, 68232744A\$, 68258786A\$, 68268591A\$, 68268592A\$, 68268593A\$, 68312697A\$, 52014632A\$, 52014775A\$

Part Description: CONDENSER, Air Conditioning

Issue Description: If it is determined that the A/C compressor does not engage due to a refrigerant leak at the receiver/drier plug on the A/C condenser, order the receiver/drier plug kit P/N 68447796A\$ and follow the repair instructions included on the instruction sheet.~

~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.