



Service Bulletin

Bulletin No.: 19-NA-204

Date: September, 2019

INFORMATION

Subject: Information on Airbag Light On - False DTC C3373 Set

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Pontiac	Vibe	2009	2009				

Involved Region or Country	North America
Condition	Some technicians may find DTC C3373 Set.
Information	If the Tech2 displays DTC C3373, disregard and use Diagnostic for B1773 in SI. ⇒ Follow the diagnostic for DTC B1773 and if required per diagnostics, replace the passenger front seatbelt tensioner per SI.

Parts Information

No parts are required for this repair.

Version	1
Modified	Released September 05, 2019

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION