

SS: 1034504 "TBB Minotour Missing A/C Ground circuit"

This Service Solution does not imply any special warranty coverage. Standard warranty guidelines and coverage apply. This Service Solution is provided to assist Dealers/Customers in resolving the issue of the factory A/C that may not work or may shut off during operation. Ground wire missing at the control board . The Cable was added to the installation diagram 3-24-2019. Any units after that date, the Ground Cable should be installed.

Applicable Vehicles

Minotours

Symptoms

Factory A/C may not work or may Shut off during operation.

Solution:

Check to see if harness 220486 has been installed. If not, add harness from AC Relay Control Panel ground terminal and mount to screw that holds ac box cover down. Refer to drawing 203010 for installation.