

---

## BRAKE and/or BRAKE SYSTEM Indicators On with DTC P1E4D-00?

### AFFECTED VEHICLES

Year	Model	Trim
2017	Accord Hybrid	ALL

**EDITOR'S NOTE:** This article replaces "MIL On with DTC P1E4D-00?", dated **October 2019**.

Is the BRAKE and/or BRAKE SYSTEM indicator on with DTC P1E4D-00 (motor angle signal malfunction)? Our initial investigation points to the motor assembly on the tandem motor cylinder.

To fix this issue, just replace the motor on the tandem motor cylinder (P/N 57032-T3Z-A20).