



# 2008 - 2010 Passat

Engine	Part	Part Number	Quantity	
2.0L FSI Turbo:	Oil Filter	06D-115-562	1	
	VW 502 00 Use synthetic oil SAE 5W-40, SAE 5W-30	N/A	4.6L (4.9qt)	
BPY	Drain Plug + Gasket	N 90813202	1	
	Pollen Filter (20K Only)	1K1-819-653-B	1	

Engine	Part	Part Number	Quantity
2.0L TSI Turbo: CCTA, CBFA	Oil Filter	06J-115-403-Q	1
	VW 502 00 Use synthetic oil SAE 5W-40, SAE 5W-30	N/A	4.6L (4.9qt)
	Drain Plug Gasket	See Tech Tip 17-12-02 Elsa Doc #2030603	1
	Pollen Filter (20K Only)	1K1-819-653-B	1

Miscellaneous	Part	Part Number	Quantity
Miscellaneous	Air Filter	1K0-129-620-D	1
	Driver's Wiper Blade	3C1955425D	1
	Passenger's Wiper Blade	3C1955426D	1
	Wiper Blade Set	3C1998002	1
	Rear Wiper Blade (Wagon Only)	3C9-955-425	1

Engine	Part	Part Number	Quantity	
3.6L VR6: BLV	Oil Filter	070-115-562	1	
	VW 502 00 Use synthetic oil SAE 5W-40, SAE 5W-30	N/A	5.5L (5.8qt)	
	Drain Plug + Gasket	N 90813202	1	
	Pollen Filter (20K Only)	1K1-819-653-B	1	
Miscellaneous	Air Filter	1K0-129-620-B	1	
	Driver's Wiper Blade	3C1955425D	1	
	Passenger's Wiper Blade	3C1955426D	1	
	Wiper Blade Set	3C1998002	1	
	Rear Wiper Blade (Wagon Only)	3C9-955-425	1	

© 2019 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

2008-2010	Engine Code		Torque Spec	
Oil drain plug Torque	2.0L	ВРҮ	M14 plug	30 Nm
			M24 plug	50 Nm
	2.0L	CCTA,CBFA	M14 plug	30 Nm
			M24 plug	50 Nm
	3.6L	BLV	M14 plug	30 Nm
			M24 plug	50 Nm
Wheel hub bolt Torque	2.0L	BPY	120 Nm	
	2.0L	CCTA,CBFA		
	3.6L	BLV		

Revised 11/11/2019

### 2008 Passat Service Reminder Reset

# Resetting the service interval display

If the maintenance service was **not** done by an authorized Volkswagen dealer or a qualified workshop, the service interval display system should be reset by your authorized Volkswagen dealer or a qualified workshop.



# Tips

Do not reset the service interval function between scheduled maintenance intervals; doing so will result in an incorrect display.

Applies to vehicles: With Multi-Function Indicator Display (MFD)

### 2009 Passat Service Reminder Reset

### Resetting the service interval display

If service was not performed by a Volkswagen dealer, the display must be reset as follows:

- Use the rocker switch on the windshield wiper lever or the buttons in the multi-function steering wheel (where applicable) to select the **Settings**.
- In the Service submenu mark the Reset menu item and press the OK button in the windshield wiper lever or the multi-function steering wheel (where applicable) to reset the service interval display. Confirm the subsequent security check with OK



- If you reset the service display yourself, the next service is displayed after 9,320 miles (15,000 km) or one year. The service interval is not determined individually.
- Do not reset the service interval function between scheduled maintenance intervals; doing so will result in an incorrect display.

## 2010 Passat Service Reminder Reset

### Resetting the Service Interval Display

Vehicles with menu display (where applicable) in the instrument cluster:

If service was not performed by a Volkswagen dealer, the display must be reset as follows:

© 2019 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

- Use the rocker switch on the windshield wiper lever or the buttons in the multi-function steering wheel (where applicable) to select the **Settings** menu.
- In the Service submenu mark the Reset menu item and press the OK button in the windshield wiper lever or the multi-function steering wheel (where applicable) to reset the Service Interval Display. Confirm the subsequent security check with OK

Vehicles without menu display (where applicable) in the instrument cluster:

- Switch off the ignition and press the 0.0 / SET button.
- Hold the 0.0 / SET button down and switch the ignition on. The service interval display is now in the reset mode.
- Release the 0.0 / SET button and within 20 seconds press the 🔁 button. After a short period, the normal display will return.



- If you reset the service display yourself, the next service is displayed after 9,320 miles (15,000 km) or one year. The service interval is not determined individually.
- Do not reset the service interval function between scheduled maintenance intervals; doing so will result in an incorrect display.