



Volkswagen



2019 Passat

| Engine | Part | Part Number | Quantity |
|-------------------------------|--|--------------------|--------------|
| 2.0L Turbo: DDSA, DDSB | Oil Filter | 06K 115 562 | 1 |
| | VW 508 00 Use synthetic oil SAE 0W-20 | N/A | 5.7L (6.0qt) |
| | Drain Plug W/Gasket | 06L 103 801 | 1 |
| | Air Filter | 5C0 129 620 B | 1 |
| | Air Filter W/Connecting Parts | 561 906 311 | 1 |

| Miscellaneous | Part | Part Number | Quantity |
|----------------------|--|------------------------|----------|
| Miscellaneous | Cabin Filter - Odor and Allergen | 1K1 819 669 | 1 |
| | Cabin Filter - Odor and Harmful Substance | 1K1 819 653 B | 1 |
| | Cabin Filter - Dust and Pollen | 1K0 819 644 B | 1 |
| | Wiper Blade – Left | 561 955 425 A | 1 |
| | Wiper Blade – Right | 561 955 426 A | 1 |
| | Battery (Amp. Req. Vary) | 000 915 105 DE* | 1 |

*VIN Required

| 2019 | Engine Code | | Torque Spec |
|------------------------------|-------------|------------|-------------|
| Oil drain plug Torque | 2.0L | DDSA, DDSB | 30 Nm |
| Wheel hub bolt Torque | 2.0L | DDSA, DDSB | 140 Nm |

Revised 11-11-2019

2019 Passat Service Reminder Reset


Resetting the oil service reminder

If the service was not performed by an authorized Volkswagen dealer or an authorized Volkswagen Service Facility, the oil service reminder can be reset as follows:

Vehicles with Premium display:

1. Switch off the ignition.
 2. Press and hold the **0.0/SET** button in the instrument cluster.
 3. Switch on the ignition.
 4. Release the **0.0/SET** button.
 5. A confirmation message appears in the display. Confirm request with the **OK/RESET** in the windshield wiper lever or the **OK** button on the multi-function steering wheel.
-

Vehicles with Basic display:

1. Switch off the ignition.
 2. Push the **0.0/SET** button in the instrument cluster and hold down.
 3. Switch on the ignition.
 4. Release the **0.0/SET** button and push the  button in the instrument cluster within about 20 seconds.
-

Resetting the inspection service reminder

If the service was not performed by an authorized Volkswagen dealer or an authorized Volkswagen Service Facility, the inspection service reminder can be reset as follows:


Vehicles with Premium display:


1. Switch off the ignition.
 2. Switch on the emergency flashers.
-


Vehicles with Premium display:

3. Press and hold the **0.0/SET** button in the instrument cluster.
4. Switch on the ignition.
5. Release the **0.0/SET** button.
6. A confirmation message appears in the display. Confirm request with the **OK/RESET** in the windshield wiper lever or the **OK** button on the multi-function steering wheel.
7. Switch off the emergency flashers.

Vehicles with Basic display:

1. Switch off the ignition.
2. Switch on the emergency flashers.
3. Push the **0.0/SET** button in the instrument cluster and hold down.
4. Switch on the ignition.
5. Release the **0.0/SET** button and push the  button in the instrument cluster within about 20 seconds.
6. Switch off the emergency flashers.

 Do **not** reset the service reminder between service intervals; otherwise, incorrect information will be displayed.

 The service reminder disappears after a few seconds or after the **OK/RESET** button on the windshield wiper lever or the **OK** button on the multi-function steering wheel has been pushed.

For current fluid capacity charts, please refer to the Maintenance section in Elsa.