



Safety Recall and Service Campaign - Technician Certification Requirements

Posted 10/17/2019

IMPORTANT:

Refer to the following matrix to determine the technician certification requirements for each specific Safety Recall or Service Campaign.

Special Courses and Additional Requirements are noted in the two columns on the far right.

Refer to the Dealer Letter of the specific Safety Recall or Service Campaign for more information.

| Safety Recall or Service Campaign | Description | Certification Level Requirements for Service Technicians / Diagnostic Specialists | | | Special Courses | Additional Requirements |
|--|---|---|--------|--------|-----------------|---|
| | | Certified | Senior | Master | | |
| Safety Recall KLF | Certain 2019 ES 300h, LC 500, LS 500, LS 500h, UX 250h Potential Loss of Power Brake Assist | | ✓ | ✓ | | |
| Limited Service Campaign (LSC) KLG / CSP 19LE05 | Certain 2011-2017 LS, 2013-2016 LS HV, 2011-2017 GS, 2016-2017 GS-F, 2013-2017 GS HV, 2010-2017 IS, 2011-2015 IS-C, 2013-2014 IS-F, 2015-2017 RC, 2015-2017 RC-F, 2011-2017 CT, 2010-2017 RX, 2010-2017 RX HV, 2015-2017 NX, 2015-2017 NX HV, 2013-2017 LX, 2013-2018 GX, 2010-2017 ES, 2013-2017 ES HV Safety Connect System - Vehicle Location Inaccurate | ✓ | ✓ | ✓ | LSC17A | |
| Safety Recall JLL | Certain 2008-2019 LX 570 Passenger Airbags Could Deactivate | ✓ | ✓ | ✓ | LSC17A | |
| Safety Recall KLE | Certain 2019 ES350 Driver Knee Airbag Replacement | ✓ | ✓ | ✓ | LSC17A | |
| Safety Recall KLD | Certain 2019 ES350 Driver Knee Airbag Replacement | ✓ | ✓ | ✓ | LSC17A | |
| Special Service Campaign (SSC) JLG | Certain 2010 GX 460 Air Injection Pumps and Air Switching Valves | ✓ | ✓ | ✓ | LSC17A | |
| Safety Recall KLC | Certain 2018 LS 500 & LS 500h Possible Partial Tread Separation of Run-Flat Tires | ✓ | ✓ | ✓ | LSC17A | |
| Special Service Campaign (SSC) KLA | Certain 2018 GS 350, RC 300, RC 350, IS 300, IS 350, RX 350, RX 350L Engine ECU Software Update | ✓ | ✓ | ✓ | LSC17A | |
| Safety Recall JSL | Certain 2008-2019 LX 570 Passenger Airbags Could Deactivate | ✓ | ✓ | ✓ | LSC17A | |
| Safety Recall JLE | Certain 2018 LS 500 Engine ECU Software Update | ✓ | ✓ | ✓ | LSC17A | |
| Safety Recall JLI/JLJ/JLK | Certain 2007-2012 ES350, 2010-2017 GX460, 2008-2009 ISF, 2006-2012 IS250, 2010-2015 IS250C, 2006-2012 IS350, 2010-2011 IS350C, 2002-2010 SC430 Front Passenger Airbag Inflator Module | ✓* | ✓* | ✓ | LSC17A | *36 months Lexus experience and L652 + LSC13B |
| Special Service Campaign (SSC) JLH | Certain 2018 LS 500/500h, 2018 NX 300/300h, 2018 RX 350L/450hL, 2017-2018 RX 350/450h Intelligent Clearance Sonar (ICS) System Reprogram | ✓ | ✓ | ✓ | LSC17A | |
| Safety Recall JLF | Certain 2007-2011 GS350, GS450h, 2006-2014 IS350, IS350C Fuel Delivery Pipe | ✓ | ✓ | ✓ | LSC17A | |
| Safety Recall JLD | Certain 2017 RX 350 Vacuum Pump | ✓ | ✓ | ✓ | LSC17A | |
| Limited Service Campaign (LSC) JLC | Certain 2017 RX350/450h Safety Connect System | | ✓ | ✓ | | |
| Safety Recall JLA | Certain 2015-2016 NX300h/200t, 2016 RX350/450h Airbag Sensor | ✓* | ✓* | ✓ | LSC17A | *L652 |
| Safety Recall JLB | Certain 2015-2018 RC-F, 2016-2018 GS-F, 2018 LC 500 High Pressure Fuel Pumps | ✓ | ✓ | ✓ | LSC17A | |
| Safety (Non-Compliance) Recall HLF | Certain 2018 GX 460 Load Carrying Capacity Modification Label | ✓ | ✓ | ✓ | LSC17A | |
| Safety Recall HLE | Certain 2010 HS 250h HV Transaxle | | ✓ | ✓ | | L071 |
| Safety Recall HLD | Certain 2006 LX 470, 2008-2013 LX 570 Driver or Front Passenger Airbag Assembly | | | ✓ | | |

| Safety Recall or Service Campaign | Description | Certification Level Requirements for Service Technicians / Diagnostic Specialists | | | Special Courses | Additional Requirements |
|------------------------------------|--|---|--------|--------|-----------------|---|
| | | Certified | Senior | Master | | |
| Safety Recall HLC | Certain 2017 ES 350 Tie Rod Lock Nut Torque | | ✓ | ✓ | | L453 |
| Limited Service Campaign (LSC) HLB | Certain 2017 MY GS 350 AWD Carpet Floor Mat Replacement | ✓ | ✓ | ✓ | LSC17A | |
| Safety Recall GLG/GLH/HLA | Certain 2006 - 2013 MY IS 250/350, 2008 - 2014 MY IS F, 2007-2012 ES 350, 2010-2017 GX 460, 2010-2015 IS Convertible Takata Air Bag | ✓* | ✓* | ✓ | LSC17A | *36 months Lexus experience and L652 + LSC13B |
| Limited Service Campaign (LSC) GLM | Certain 2015 RC350/RC-F & Certain 2014-2015 IS 250/350 Rear Wheel Arch Corrosion | | ✓ | ✓ | | |
| Safety Recall GLB | 2004-2006 GX 470 & 2003-2006 LX 470 SRS ECU | | ✓ | ✓ | | |
| Special Service Campaign (SSC) GLP | Certain 2015-2017 MY NX 200t & NX 300h ABS Software Update | ✓ | ✓ | ✓ | LSC17A | |
| Limited Service Campaign (LSC) GLL | Certain 2016 MY RX 350 & RX 450h Power Rear Hatch ECU | ✓ | ✓ | ✓ | LSC17A | |
| Safety Recall GLJ | 2011-2012 MY CT 200h Curtain Shield Airbag | | | ✓ | | |
| Safety Recall GLK | Supplement to CLE - 2010 Model Year HS250h Reinspection Required - Rear Lower Suspension Arm No. 1 | | ✓ | ✓ | | L453 |
| Limited Service Campaign (LSC) GLI | Certain 2016 MY RC 300 AWD & RC 350 AWD Carpet Floor Mat Replacement | ✓ | ✓ | ✓ | LSC17A | |
| Special Service Campaign (SSC) GLE | Certain 2016 MY RX 450h Fuel Tank Ring Replacement | | ✓ | ✓ | | |
| Limited Service Campaign (LSC) GLD | Certain 2015 MY GS 350, LS 460 RC 350 and certain 2016 MY GX 460, IS 200t/300/350, NX 200t Safety Connect System | | ✓ | ✓ | | |
| Safety Recall GLC | Certain 2016 MY ES 350 & RX 350 Brake Actuator Inspection/Replacement | | ✓ | ✓ | | |
| Safety Recall GLA | Certain 2016 Model Year RX355, RX400h Driver Knee Airbag Inspection and Replacement | | ✓ | ✓ | | |
| Special Service Campaign (SSC) FLF | Certain 2010 - 2012 Model Year HS 250h Vehicles Fuel Pump and Wire Harness Replacement | | ✓ | ✓ | | |
| Safety Recall FLE | Certain 2013 - 2015 Model Year ES350, ES300h Pre-Collision System | | ✓ | ✓ | | |
| Safety Recall FLD | Certain 2007 Model Year RX400h Powertrain and Hybrid ECU Software Update | ✓* | ✓ | ✓ | LSC17A | *L623 |
| Safety Recall FLC | 2015 Model Year NX 200t Vehicles Brake Actuator | | ✓* | ✓* | | *With Self-Paced Module HL511A |
| Limited Service Campaign (LSC) FLB | Certain 2010 Model Year RX450h Vehicles Oxygen Sensor Replacement | | ✓ | ✓ | | |
| Limited Service Campaign (LSC) FLA | 2013 Model Year GS350 and GS450h Vehicles Front Passenger Supplemental Restraint System | | ✓ | ✓ | | L652 |
| Safety Recall ELG | For Areas of High Absolute Humidity 2002 through 2005 Model Year SC 430 Vehicles Front Passenger Air Bag Inflator Module | ✓* | ✓* | ✓ | LSC17A | *36 months Lexus experience and L652 + LSC13B |
| Safety Recall ELF | Certain 2007-2011 GS350, 2007-2011 IS350, 2010 IS350C (2GR-FE Engine), Certain 2006 GS300 (3GR-FE Engine), Certain 2006-2010 IS250, 2010 IS250C (4GR-FSE Engine), Certain 2007-2010 LS460 (1UR-FSE Engine), 2008-2011 LS600hL (2UR-FSE Engine), Certain 2008-2011 GS460 (1UR-FSE Engine), Certain 2007-2011 GS450h (2GR-FSE Engine), Certain 2008-2011 IS-F (2UR-GSE) Vehicles Fuel Pressure Sensor Gasket | ✓ | ✓ | ✓ | LSC17A | |
| Limited Service Campaign (LSC) ELE | Certain 2008 through 2012 Model Year IS F Vehicles Engine Cooling Fans | | ✓ | ✓ | | |
| Safety Recall ELD | Certain 2015 MY RX 350 Vehicles Equipped with 2GR-FE Engine Potential Fuel Delivery Pipe Leak | ✓ | ✓ | ✓ | LSC17A | |
| Safety Recall ELB | 2013 GS 350 Vehicles Brake Pedal Load Sensing Switch | | ✓ | ✓ | | |
| Safety Recall ELA | 2012-2013 RX350 Brake Actuator Reprogramming | ✓ | ✓ | ✓ | LSC17A | |

| Safety Recall or Service Campaign | Description | Certification Level Requirements for Service Technicians / Diagnostic Specialists | | | Special Courses | Additional Requirements |
|------------------------------------|---|---|--------|--------|-----------------|---|
| | | Certified | Senior | Master | | |
| Safety Recall DSC | 2002-2004 SC430 Vehicles Front Passenger Air Bag Inflator Module | ✓* | ✓* | ✓ | LSC17A | *36 months Lexus experience and L652 + LSC13B |
| Safety Recall DLG | 2006-2011 IS350, 2010-2011 IS350C, 2007-2011 GS350 2GR-FSE Intake VVT Actuator Gear | | ✓ | ✓ | | |
| Safety Recall DLF | 2006-2008 RX400h Intelligent Power Module (IPM) Replacement | | ✓ | ✓ | | L071 |
| Safety Recall DLD | 2010 Model Year HS250h Vehicles Brake Booster Pump Assembly (Accumulator) | | | | | *It up to the Dealer's discretion as to which technicians can perform this Safety Recall. |
| Safety Recall DLC | 2002-2003 SC430 Front Passenger Airbag Inflator Module | ✓* | ✓* | ✓ | LSC17A | *36 months Lexus experience and L652 + LSC13B |
| Safety Recall CSE | Supplement to CLE - 2010 Model Year HS250h Reinspection Required - Rear Lower Suspension Arm No.1 | | ✓ | ✓ | | L453 |
| SSC BSL | 2010 RX350, 2008 - 2010 LX570 Smart Stop Technology | ✓ | ✓ | ✓ | LSC17A | |
| Limited Service Campaign (LSC) 9LH | 9LH Extension; 2007-2009 RX 350 and 2007-2008 ES 350 Vehicles 2GR-FE (V6) Engine VVT-i Oil Hose Replacement | | ✓ | ✓ | | |