

complaint: LP issues. burned through half a tank in one evening. when filling it valve doesn't shut when full. relief valve never had air or gas come out.

customer states turned on fridge one night and lost 20% of LP and now nothing will turn on

correction: needs new regulator

labor: 0.60 hr

parts: 06-0096 low press 2 stage LP reg (ntp) \$46.31

- 1) Customer states LP leak smells at exterior P/S rear of coach
T-Shoot and found LP leak at LP regulator .
Necessary to replace LP regulator , need to remove old and
The brackets , cover , hose and install new regulator , need
To connect hoses , reinstall bracket , cover and perform
A leak test . (2.2)**