

Literature Information

All  
1902

Valid Advanced Technical Information (ATI) Bulletins

Binder - Camp., Lit., Train., Warr.

This bulletin replaces bulletin 1902, dated 4-2-2019.

Yes, Filed OK

The following is a list of all current Advanced Technical Information Bulletins published by Parts & Service Publications. If you are missing any of the following bulletins, please download and print the required bulletins from the Document Repository.

✓	Group	Part ID	Number	Model	Subject	Date
<input type="checkbox"/>	0	9124	0302	All With CDR23 Radio	CDR23 Coding and Basic Troubleshooting	2-14-03
<input type="checkbox"/>	0		0602	9x6	Diagnosing Alarm Complaints on 9x6 Vehicles	7-28-06
<input type="checkbox"/>	0		0603	Cayenne (9PA)	Diagnosing Unwanted Alarm Activation	7-28-06
<input type="checkbox"/>	0		0700	Sports Cars	Key Remote Control Not Working or Losing Settings	1-16-07
<input type="checkbox"/>	0		0703	Sports Cars	Check Engine Light Illuminated/Fault Code Entry in PQIS	8-13-07
<input type="checkbox"/>	0		0704	Cayenne (9PA)	Check Engine Light Illuminated/Fault Code Entry in PQIS	8-13-07
<input type="checkbox"/>	0		0705	All	Long Sleeve Nitrile Gloves For Fuel System Work	11-27-07
<input type="checkbox"/>	0		0901	All	Cleaning & Detailing Engine Compartment	8-5-09
<input type="checkbox"/>	0		0902	Panamera (970)	PDI - Important Information	2-4-10
<input type="checkbox"/>	0		1003	Panamera/Cayenne (92A)	Control Unit Coding & Online Teaching w/PIWIS Tester II	11-19-10
<input type="checkbox"/>	0		1202	Panamera	Missing or Incomplete VINs	8-29-12
<input type="checkbox"/>	0	0911	1301	All	Vehicle Fluid Analysis Program	4-15-13
<input type="checkbox"/>	0		1302	All	PIWIS Tester II Overview	4-23-13
<input type="checkbox"/>	0	0106	1401	All 2 Wheel 9x1 & 970	Preparation For Rolling Dyno Use	2-4-14
<input type="checkbox"/>	0	0905	1403	All	Labor Time & Parts Claims PIWIS Tester III Issue	7-18-16
<input type="checkbox"/>	0	0335	1501b	All w/Manual Trans	Granting CPO Warranty in Case Of Over-Rev Entry in VAL	1-16-15
<input type="checkbox"/>	0	0335	1501a	All w/Manual Trans	Granting CPO Warranty in Case Of Over-Rev Entry in VAL	1-16-15
<input type="checkbox"/>	0	0335	1601	All	Vehicle Analysis Log Types	4-22-16
<input type="checkbox"/>	0		1602	All	Approval & Support Management Program	1-30-19
<input type="checkbox"/>	0	0351	1603	All	Tire Sealant Life - Expiration Date	7-29-16
<input type="checkbox"/>	0	0335	1701	Cayman GT4 (981)	GT4 Clubsport Information & Technical Support	2-3-17
<input type="checkbox"/>	0	0905	1702	All	PT3G Diagnostic Application Restart	2-15-17
<input type="checkbox"/>	0	0905	1703	All	PT3G VCI Troubleshooting	3-20-17
<input type="checkbox"/>	0	0905	1704	All	File Transfer Through PPN	3-20-17
<input type="checkbox"/>	0	0905	1705	All	PT3G Extended Log Transfer	3-20-17
<input type="checkbox"/>	0	0905	1706a	Panamera (971)	DTC U110300 Production Mode is Active	7-20-17
<input type="checkbox"/>	0	0905	1706b	Panamera (971)	DTC U110300 Production Mode is Active	7-20-17
<input type="checkbox"/>	0	0905	1707	Panamera (971)	Deactivating Transport Mode	9-21-17
<input type="checkbox"/>	0	0905	1801	All	Creating an Extended Log	3-30-18
<input type="checkbox"/>	0	0905	1802	All	Creating Techline Assistance Request	09-01-19
<input type="checkbox"/>	1	1901	0201	911 (996)	Coolant Light Flashing	7-30-02
<input type="checkbox"/>	1	1938	0202	All	Cooling System Additives	7-30-02
<input type="checkbox"/>	1	1348	0203	All	Crankshaft Measurement To Case	7-30-02

All  
1902

## Literature Information

✓	Group	Part ID	Number	Model	Subject	Date
<input type="checkbox"/>	1	1731	0204	911 (993)	Secondary Oil Filter Bleed back PN 993 107 203 03	10-14-02
<input type="checkbox"/>	1	1378	0205	911 (993)	Misfire Faults Diagnosis Tips	11-22-02
<input type="checkbox"/>	1	1348	0501	Sports Cars (996)	Oil Leak At Crankshaft Pulley	5-16-05
<input type="checkbox"/>	1	1359	0502	9x6	Handling PTFE Crankshaft Seals	11-07-05
<input type="checkbox"/>	1	1359	0601	911 GT3 (996/997)	Handling PTFE Crankshaft Seals	6-9-08
<input type="checkbox"/>	1	1359	0602	9x6/9x7	Crankshaft Measurement To Crankshaft Tool 9699/1	3-1-05
<input type="checkbox"/>	1	1901	0801	9x7	Replacing Coolant Reservoir Cap	9-4-08
<input type="checkbox"/>	1	1591	0802	Cayenne Turbo (9PA)	Valve Cover With Integrated Oil Separator	10-14-08
<input type="checkbox"/>	1		0803	Cayenne (9PA)	MY 2009 V8 Engine Component Changes	1-20-09
<input type="checkbox"/>	1	1001	0902	All	Authorization For PCM 3.0, DFI And PDK Replacements	3-10-09
<input type="checkbox"/>	1	1010	0903	911 GT3 (997)	Engine Oil Leaks	3-16-09
<input type="checkbox"/>	1	1711	1100	Cayenne (92A)	Oil Level Warning	2-18-11
<input type="checkbox"/>	1	1584	1201	Cayenne (92A) & Panamera	Camshaft Adjuster Diagnosis	12-3-12
<input type="checkbox"/>	1	1701	1301	Cayenne V6 (92A)	V6 Engine Oil Level Warning "Above Max"	1-8-13
<input type="checkbox"/>	1	1001	1302	All	Engine Oil Sample Request	4-15-13
<input type="checkbox"/>	1	1726/9752	1303	All	Oil Ingress into The Engine Wiring Harness	7-17-13
<input type="checkbox"/>	1	1961	1304	Cayenne (9PA)	Coolant Pipe Inspection	12-12-13
<input type="checkbox"/>	1	1901	1401	All	Coolant Gelling After Extreme Engine Overheating	9-15-14
<input type="checkbox"/>	1	1701	1602	S E-Hybrid (92A/970)	S E-Hybrid Oil Level	1-31-17
<input type="checkbox"/>	1	1582	1701	911 (991)	Oil Leak From The Engine Near Cylinder 6	5-17-17
<input type="checkbox"/>	1	1945	1703	Cayenne PHEV (92A)	Low Temperature Coolant Pump Fault Present	7-26-17
<input type="checkbox"/>	1	1945	1801	Cayenne PHEV (92A)	Additional Coolant Pump Fault POC4700 Causes MIL	2-8-18
<input type="checkbox"/>	1	1570	1802	971, 9YA	Oil Leak From Cylinder Head of 3.0l & 2.9l V6 Engines	12-21-18
<input type="checkbox"/>	2	2470	0201	All	DME Programming Error Codes	7-30-02
<input type="checkbox"/>	2	2470	0202	All	Fault Code P1691 Stored in DME	7-30-02
<input type="checkbox"/>	2	2000	0203	All	Oxygenated Fuel Additives	7-30-02
<input type="checkbox"/>	2	2601	0204	911 (996)	Sport Exhaust System Low Speed Noise	9-13-02
<input type="checkbox"/>	2	2025	0301	9x6 All w/DME 5.2.2 & 7.2	Activated Carbon Canister	2-14-03
<input type="checkbox"/>	2	2470	0303	Sports Cars (9x6)	Secondary Air Injection Fault P0410, P1411	5-23-03
<input type="checkbox"/>	2	2470	0501	9x7	M-Option Programming Of DME	10-10-05
<input type="checkbox"/>	2	1978	0502	Boxster (987)	Engine Coolant Temperature Sensor	10-24-05
<input type="checkbox"/>	2	2027	0601	Sports Cars	ORVR Diagnosis	5-31-06
<input type="checkbox"/>	2	2025	0603	9x7	Carbon Canister Smoke Testing - Fuel Tank Flange Leaks	12-15-06
<input type="checkbox"/>	2	2010	0604	Cayenne (9PA)	In-Tank Fuel Delivery - Diagram	1-20-06
<input type="checkbox"/>	2	2025	0605	9x7	Carbon Canister - Leak Detection Module Information	8-31-06
<input type="checkbox"/>	2	0810/2446	0700	Cayenne V6	V6 Engine Noise	11-30-07
<input type="checkbox"/>	2	2470	1002	911 Turbo (997)	Engine Noise	9-1-10
<input type="checkbox"/>	2	2007	1003	9x7	Difficulty Filling With Fuel - States W/EVR II Nozzles	10-29-10
<input type="checkbox"/>	2	2010	1101	Cayenne V6 (92A)	Re-Programming DME	3-14-11
<input type="checkbox"/>	2	2048	1102	Cayenne V6 (92A)	Check Engine Light On and Fault P0456 Stored in DME	9-2-11
<input type="checkbox"/>	2	2048	1103	Cayenne S/T (92A)	Check Engine Light On and Fault P0456 Stored in DME	9-2-11
<input type="checkbox"/>	2	2469	1201	Cayenne V6 (9PA)	Check Engine Light On and Fault P0421 or P0432	1-24-12

Literature Information

All  
1902

✓	Group	Part ID	Number	Model	Subject	Date
☐	2	2601	1401	918 Spyder	918 Spyder Top Exhaust, Debris Introduction	8-27-14
☐	2	2470	1402	Cayenne VR6 & Diesel	Check Engine Light Activated and P150A00 Stored	10-3-14
☐	2	2010	1403	9x1	Squeak and/or Rattle From Dash or Instrument Cluster	12-16-14
☐	2	2470	1502	Macan (95B)	Check Engine Light in Illuminated and Fault P0299	8-27-15
☐	2	2601	1503	Macan (95B)	Rattle From Under Vehicle Center Exhaust Pipe	7-23-15
☐	2	2760	1504	Cayenne (92A)	92A Starter Seizes in Cold Conditions	3-29-16
☐	2	2791	1601	Cayenne S E-Hybrid	Hybrid Warnings & Faults	2-10-16
☐	2	2706	1602	911 GT3, Cayman GT4	Installation & Care of Li-ion Battery	9-23-16
☐	2	2706	1701	All	Use of Deutronic 90A Power Supply w/12V Lithium	2-20-17
☐	2	2454	1702	Panamera 4S/T (971)	Fault P029900 Stored in DME Due To Loose Vacuum Line	6-19-18
☐	2	2706	1703	All w/AGM Batteries	Low 12V Battery May Cause Misdiagnosis	4-25-17
☐	2	2470	1704	Cayenne S/GTS (92A)	Oversensitive Knock Detention & Cruise Control	5-18-17
☐	2	2171	1705	911 (991)	Blue Smoke from the Exhaust	9-29-17
☐	2	2708	1707	918, 970, 971, 92A	Flood Damaged Hybrid Vehicles	9-13-17
☐	2	2706	1801	911 GT3 (991)	Lightweight Li-ion Starter Battery Not Approved For MY18	3-29-18
☐	2	2708A	1802	Panamera 4 E-Hybrid (971)	Cooling System Fault POC4A00	5-24-18
☐	2	2473	1804	Panamera (971)	Rear O2 Sensor Improvement	10-2-18
☐	2	2873	1805	Cayenne (92A)	Cayenne V6 Crankshaft Position Sensor	8-1-18
☐	2	2048	1806	Macan (95B)	Leak Diagnostic Pressure Switch	8-16-18
☐	<b>2</b>	<b>2708</b>	<b>1706</b>	<b>918, 970, 971, 92A</b>	<b>Packaging &amp; Test Log Requirements For HV Battery Returns</b>	<b>4-12-19</b>
☐	<b>2</b>	<b>2470</b>	<b>1901</b>	<b>Cayenne (92A)</b>	<b>Diesel, Setting Ready Status</b>	<b>5-16-19</b>
☐	<b>2</b>	<b>2785</b>	<b>1807</b>	<b>Cayenne (9YA)</b>	<b>Adaptive Cruise Control Warning Along with ZFAS Faults</b>	<b>8-6-19</b>
☐	<b>2</b>	<b>2785</b>	<b>1902</b>	<b>911 Carrera (992)</b>	<b>Li-Ion Warning Label on Battery Bracket in Vehicles with AGM Battery</b>	<b>9-27-19</b>
☐	3	3735	0201	All	Tiptronic Transmission Will Not Up Shift	7-30-02
☐	3	3701	0202	911 (996)	Tiptronic/Driveline Noise	11-19-02
☐	3	3701	0203	911 Turbo (996)	Tiptronic/Driveline Noise	11-19-02
☐	3		0401	9x6	Remanufactured 6-Speed Transmission Filled With Oil	10-7-04
☐	3	3435	0800	Sports Cars	6-Speed Getrag Transmission	3-7-08
☐	3	3935	1001	Panamera	Cardan Shaft Squealing Noise During Light Acceleration	6-24-10
☐	3	3965	1101	Cayenne (92A)	Shudder/Vibration On Acceleration	10-2-12
☐	3	3240	1701	918 Spyder	Shortened Bolts on 3 918 Spyderys	4-25-17
☐	3	3435	1702	Boxster/Cayman (982)	Does Not Move When in Third Gear	9-12-17
☐	3	3435	1703	Cayman GT4 (981)	Does Not Move When in Third Gear	9-12-17
☐	3	3730	1704	Panamera (971)	Rough Gear Changes in First and Second	1-6-18
☐	4	4495	0401	Cayenne (9PA)	Pulling Due To Road Crown	9-3-04
☐	4	4077/78, 4290/91	0402	9x6/9x7	Connection Rod (F & R) For Stabilizer	12-10-04
☐	4	4412/23/40/95	0501	Cayenne (9PA)	Steering Wheel Vibration	3-23-05
☐	4	4088	0502	911 GT2/GT3 (996)	Heim Joint On Strut Support Plate	3-28-05
☐	4	4434	0701	Cayenne (9PA)	Tire Pressure Monitoring System Fault Tree Analysis	8-13-07
☐	4	4302/4315	0702	Cayenne (9PA)	Level Adjustment Fault Code 1772 - Pressure Sensor	12-5-07
☐	4	4898	0800	Cayenne (9PA)	Power Steering System Hydraulic Pump	3-28-08
☐	4	4560	0801	Cayenne (9PA)	Steering Angle Sensor	4-8-08

All  
1902

## Literature Information

✓	Group	Part ID	Number	Model	Subject	Date
<input type="checkbox"/>	4	4560	0802	Sports Cars (9x7)	Steering Angle Sensor	4-8-08
<input type="checkbox"/>	4	4434	0803	Sports Cars (9x7)	Tire Pressure Monitoring	5-12-08
<input type="checkbox"/>	4	46..	0804	911 Turbo (997)	Brake Noise - Rear Axle (Squealing)	10-30-08
<input type="checkbox"/>	4	4400	0900	Sports Cars (9x7)	Tire Pressure Settings	8-24-09
<input type="checkbox"/>	4	4400	0901	Cayenne (9PA)	Tire Pressure Settings	8-24-09
<input type="checkbox"/>	4	4434	0902	Sports Cars (9x7)	Tire Pressure Monitoring Control Unit Ground	8-24-09
<input type="checkbox"/>	4	4538	0903	Cayenne (9PA)	Brake Booster Distance Sensor	9-28-09
<input type="checkbox"/>	4		0904	Panamera S/Turbo	PASM: Level Lowered/Air Loss During Transport	10-29-09
<input type="checkbox"/>	4	4741	1001	Cayenne (9PA)	Brake Squeal	2-5-10
<input type="checkbox"/>	4	4405	1002	Cayenne Turbo/GTS	Wheel Offset	3-3-10
<input type="checkbox"/>	4	4530	1003	Cayenne (9PA)	PSM Control Unit Actual Value Pressure Reading	5-10-10
<input type="checkbox"/>	4	4708	1004	All	Recommended Brake Fluid Tester	11-5-10
<input type="checkbox"/>	4	4343	1101	Panamera	Rear Air Suspension Springs	2-16-11
<input type="checkbox"/>	4	4810	1103	Panamera	Multifunction Steering Wheel	5-20-11
<input type="checkbox"/>	4	4638	1105	Cayenne (92A)	Rear Brake Noise	9-22-11
<input type="checkbox"/>	4	4650	1201	Cayenne (92A)	Front Brake Noise	1-17-12
<input type="checkbox"/>	4	4894	1202	Panamera	Power Steering Lines	6-14-12
<input type="checkbox"/>	4	4683	1301	9x1, 92A & 970	Electric Parking Brake Calibration	5-2-13
<input type="checkbox"/>	4	4407	1302	Cayenne (9PA)	Wheel Bolts	5-24-13
<input type="checkbox"/>	4	4777	1303	Panamera S Hybrid	Fault P055600 Brake Vacuum System Fault Stored	6-28-18
<input type="checkbox"/>	4	4440	1304	All	Front Tire Scrubbing	11-26-13
<input type="checkbox"/>	4	4636	1402	9x1	New Front Brake Pads	12-5-14
<input type="checkbox"/>	4	46xx	1403	All	Brake Noise Due To Foreign Agents or Materials	2-28-14
<input type="checkbox"/>	4	4303	1404	991 w/PDCC	PDCC Fault 001005	3-7-14
<input type="checkbox"/>	4	4651	1405	All w/PCCB	PCCB (3rd Gen) Rotor Test Sheet	7-24-14
<input type="checkbox"/>	4	4662	1406	911 GT3 (991)	Hold Function	8-1-14
<input type="checkbox"/>	4	4511	1407	Cayenne (92A)	ABS Wheel Speed Sensor Kit	8-7-14
<input type="checkbox"/>	4	4560	1408	All	Brake Rotor Cleaning	11-4-14
<input type="checkbox"/>	4	4301	1501	Panamera	Air Suspension Diagnosis	1-28-15
<input type="checkbox"/>	4	4407	1502	All	Thatcham Wheel Lock Information	4-23-15
<input type="checkbox"/>	4	4651	1503	911 (991)	Clicking Noise From Front PCCB Rotors	5-10-17
<input type="checkbox"/>	4	4511/4515	1504	Sports Cars (9x1)	Wheel Speed Sensor & Harness	10-8-15
<input type="checkbox"/>	4	4440	1505	918 Spyder/911 GT3 RS	Michelin Pilot Sport Cup 2 Tires	11-25-15
<input type="checkbox"/>	4	4407	1506	All	Center Locking Wheel Nut Tightening	11-6-18
<input type="checkbox"/>	4	4440	1601	All	Cold Temperatures and Pilot Sport Tires	1-15-16
<input type="checkbox"/>	4	4020	1602	Sports Cars (9x1)	Suspension Bushings Leaking	2-9-16
<input type="checkbox"/>	4	4434	1604	All	Tire Pressure Monitoring Systems Operation	3-11-16
<input type="checkbox"/>	4	4206	1606	Cayman GT4	Repositioning Subframe for Chassis Alignment	4-11-16
<input type="checkbox"/>	4	4268	1701	918 Spyder	Clicking At The Rear Wheels During Cornering	3-15-17
<input type="checkbox"/>	4	4495	1702	Macan (95B)	Alignment Adapter VAS 6918 Clarification	3-23-17
<input type="checkbox"/>	4	4828	1703	Macan (95B)	Steering Wheel Shaft Seal Noise	5-19-17
<input type="checkbox"/>	4	4511	1704	911 (991)	Wheel Speed Sensor Faults	6-2-17

Literature Information

All  
1902

✓	Group	Part ID	Number	Model	Subject	Date
<input type="checkbox"/>	4	4440	1705	911 (991), 918 Spyder	UHP Tire Application Tables	11-8-17
<input type="checkbox"/>	4	4636	1801	All	Brake Squeal	2-5-18
<input type="checkbox"/>	4	43160	1802	Panamera (971)	PASM CU Programming Issues During WH29 & Faults	4-23-18
<input type="checkbox"/>	4	4XXX	1803	918 Spyder	Loose or Damaged M8 Threaded Inserts For Engine Panel	4-13-18
<input type="checkbox"/>	4	46XX	1804	All	New Porsche Classic & AfterSales Brake Fluid	5-30-18
<input type="checkbox"/>	4	4636	1805	Macan S (95B)	Front Brake Pad with Different Noise Characteristic	5-14-18
<input type="checkbox"/>	4	4617	1807	Panamera (971)	Front Brake Backing Plate Bolts	6-22-18
<input type="checkbox"/>	4	4085	1808	911 GT3/GT3 RS (991)	Front Strut Lift Leaks	7-20-18
<input type="checkbox"/>	4	4407	1809	918 Spyder	Clicking at the Rear Wheels During Hard Cornering	11-14-18
<input type="checkbox"/>	4	4651/4654	1810	911 GT2RS, GT3/RS (991)	Loose M6 Screws Securing PCCB Rotors to Wheel Hub	11-17-18
<input type="checkbox"/>	4	4650/4653	1811	911 GT2RS, GT3/RS (991)	Noise Emitting from Front and Rear Axle Wheel Assemblies	11-27-18
<input type="checkbox"/>	<b>4</b>	<b>4683</b>	<b>1901</b>	<b>991, 982</b>	<b>Parking Brake Adjustment / Calibration Difficult</b>	<b>5-8-19</b>
<input type="checkbox"/>	4	4651	1503	911 (991)	Clicking Noise From Front PCCB Rotors	8-1-19
<input type="checkbox"/>	5	5103	0201	911 (996)	Knocking Noise In Roof Panel Over Bumps	7-20-02
<input type="checkbox"/>	5	5717	0301	Cayenne (9PA)	Door Lock Module Operation	3-28-03
<input type="checkbox"/>	5	5789	0701	Cayenne (9PA)	Coding Rear Comfort Control Unit In Cayenne	10-1-07
<input type="checkbox"/>	5	5087	1002	Panamera	Front Cowl Removal	7-19-10
<input type="checkbox"/>	5	5522	1101	911 GT2 RS (997)	Carbon Fiber Components	3-22-10
<input type="checkbox"/>	5	5518	1501	Macan (95B)	Front Hood Upper Latch Fine Adjustment	8-27-15
<input type="checkbox"/>	5	5053	1502	Cayenne (92A)	Cayenne Body Drains	10-8-15
<input type="checkbox"/>	5	5x00/5000	1601	All	Paint & Glass Defect Documentation	7-8-16
<input type="checkbox"/>	5	LXXX	1701	All	Clear Coat Imperfections	1-31-17
<input type="checkbox"/>	5	5000	1703	Panamera (971)	Imperfections in Seam Sealer	4-26-17
<input type="checkbox"/>	5	5004	1704	911 (991), 982	Front End Inner Structural Parts Differences	6-8-17
<input type="checkbox"/>	5	5568	1705	92A, 970	Rear Lid FC 00001E	11-30-17
<input type="checkbox"/>	5	5192	1801	911 GT3 (991)	Front Cover Fins Not For 911 GT3 Touring Model	1-31-18
<input type="checkbox"/>	5	5537	1802	Panamera (971)	Replacing Fuel Filler or Charging Door Flap	11-30-18
<input type="checkbox"/>	5	5759	1803	Boxster/Cayman (982)	Door Guides Creaking	6-15-18
<input type="checkbox"/>	5	5103/5522	1804	911 Turbo S/GT2 RS (991)	Paint Bubbles in Carbon Fiber Parts	7-20-18
<input type="checkbox"/>	5	5711	1901	Macan (95B)	Outside Door Handle Cracks/Breaks	1-17-19
<input type="checkbox"/>	<b>5</b>	<b>55730</b>	<b>1902</b>	<b>92A, 9YA, 95B, 970, 971</b>	<b>Rear Lid Strut Diagnosis</b>	<b>2-25-19</b>
<input type="checkbox"/>	6	6658	0201	911 Turbo (996)	Spoiler Bleed Procedure	7-30-02
<input type="checkbox"/>	6	6683	0301	Cayenne (9PA)	Front License Plate - Additional Installation Instructions	3-14-03
<input type="checkbox"/>	6	6440	0302	Cayenne (9PA)	High-Pitched Noise From Window Area	5-23-03
<input type="checkbox"/>	6	6924	0303	911 (996)	Seatbelt Buckle Diagnosis - Airbag System Faults 44-51	6-12-03
<input type="checkbox"/>	6	6924	0304	Boxster (986)	Seatbelt Buckle Diagnosis - Airbag System Faults 44-51	6-12-03
<input type="checkbox"/>	6	6953	0602	Sports Cars	Installing A New POSIP Triggering Unit	8-22-06
<input type="checkbox"/>	6		0801	Sports Cars (9x7)	Interior Rearview Mirror Becomes Detached	5-23-08
<input type="checkbox"/>	6	6412	0802	Cayenne (9PA)	Thermally Insulated Glass - Interference	10-1-08
<input type="checkbox"/>	6	69..	0900	Cayenne (9PA)	Airbag Control Unit Programming	2-13-09
<input type="checkbox"/>	6	6982	0901	Sports Cars (9x7)	Diagnosis of Passenger Airbag OFF Indicator	3-5-09
<input type="checkbox"/>	6	6658	0902	Carrera GT	Spoiler Raises But Does Not Lower Automatically	4-1-09

✓	Group	Part ID	Number	Model	Subject	Date
<input type="checkbox"/>	6	6128	0904	Boxster (987)	Convertible Top Cover	8-7-09
<input type="checkbox"/>	6	6959	0905	Sports Cars (9x7)	Int. Cleaning/Care Of The "Passenger Airbag Off" Light	10-26-09
<input type="checkbox"/>	6	6959A	0906	Panamera	Passenger Airbag Off Light Remains On With Empty Seat	10-29-09
<input type="checkbox"/>	6	6953	1001	Sports Cars (9x7)	Locking POSIP Control Unit	9-17-10
<input type="checkbox"/>	6	6830	1101	Panamera	Front Cup Holders	6-14-11
<input type="checkbox"/>	6	6911	1102	Boxster/Cayman (987)	Incorrectly Manufactured Seat Belt Anchor	7-20-11
<input type="checkbox"/>	6	6911	1103	911 (997)	Incorrectly Manufactured Seat Belt Anchor	7-20-11
<input type="checkbox"/>	6	6440	1104	911 Cabriolet (997)	Cabriolet Front Window Reverses Direction	7-26-11
<input type="checkbox"/>	6	6696	1301	Cayenne (All)	Trailer Control Unit & Electronic Brake Controller	8-14-17
<input type="checkbox"/>	6	6901	1302	Sports Cars (9x1)	Airbag Faults: Below Lower Limit	7-10-13
<input type="checkbox"/>	6	6689	1303	Cayenne (92A)	Exterior Review Mirror Wind Noise	12-06-13
<input type="checkbox"/>	6	6440	1401	Cayenne (92A)	Wind Noise From Window	1-17-14
<input type="checkbox"/>	6	6652	1502	918 Spyder	Care of Vinyl Wrapped Vehicles	12-17-15
<input type="checkbox"/>	6	6101	1601	Sports Cars (981)	Convertible Top Actual Values	5-16-16
<input type="checkbox"/>	6	6956	1602	Macan (95B)	Passenger Airbag Warning Along w/Fault B121400	7-18-16
<input type="checkbox"/>	6	6458	1701	Panamera (971)	Removing Power Window Switch G2	3-16-17
<input type="checkbox"/>	6	6128	1702	9x1 Convertible	Convertible Top Rear Window Frame	4-26-17
<input type="checkbox"/>	6	6953	1801	911 (991) Gen. II & 982	Airbag Warning Along With Fault Codes 002502/002602	1-26-18
<input type="checkbox"/>	6	6966	1802	911 (991), Cayman (982)	New Curtain Style Airbags	3-29-18
<input type="checkbox"/>	6	6101	1803	911 Targa 4/4S/4 GTS (991)	Top Faults & Adjustments	6-5-18
<input type="checkbox"/>	6	6005-6006	1804	All	New Lubricant for Sunroof/Sliding Roof Mechanisms	8-7-18
<input type="checkbox"/>	6	6412	1901	All	Paint & Glass Defect Documentation	1-30-19
<input type="checkbox"/>	6	68270	1902	911 (991)	Rear View Mirror Falls Off Windshield	2-25-19
<input type="checkbox"/>	<b>6</b>	<b>6006</b>	<b>1903</b>	<b>970, 971, 92A, 9YA, 95B</b>	<b>Panoramic Roof Water Management</b>	<b>9-17-19</b>
<input type="checkbox"/>	<b>6</b>	<b>6696</b>	<b>1904</b>	<b>Cayenne (all), Macan (all)</b>	<b>Trailer Control Unit &amp; Electronic Brake Controller Info</b>	<b>4-2-19</b>
<input type="checkbox"/>	<b>6</b>	<b>6953</b>	<b>1905</b>	<b>Panamera (971)</b>	<b>971 Airbag Warning with High Cabin Temperature</b>	<b>9-27-19</b>
<input type="checkbox"/>	7	7293	0301	Cayenne (9PA)	Drivers Seat Memory Does Not Retain Memory Positions	6-27-03
<input type="checkbox"/>	7	72..	0700	Sports Cars (9x7)	Power Seat Controls Stuck	12-4-07
<input type="checkbox"/>	7	72xx	0906	Sports Cars (9x7)	Difficulty Programming 9x7 Keys	10-19-09
<input type="checkbox"/>	7	7402	1601	Panamera (970)	Panamera (970) Seat Frame Superseded	6-24-16
<input type="checkbox"/>	8	8745	1301	All	Air Conditioning Diagnosis	6-17-13
<input type="checkbox"/>	8	8530	1401	Sports Cars (9x1)	Air Conditioning Blower Motor Diagnosis	10-3-14
<input type="checkbox"/>	8	8760	1501	Macan (95B)	Air Conditining Airflow Drops While Fan is Running	8-4-15
<input type="checkbox"/>	8	8701	1502	S E-Hybrid (92A) & (970)	Parking Pre-Climitization Retrofit	12-18-15
<input type="checkbox"/>	8	8700	1701	Cayenne/Panamera	PHEV AC Shut Off Valves Diagnosis	2-20-17
<input type="checkbox"/>	8	8700	1702	All	AC System Dye & Leak Diagnosis	2-20-17
<input type="checkbox"/>	8	8700	1704	All	AC Small Leak Diagnosis	8-11-17
<input type="checkbox"/>	8	8734	1705	S E Hybrid 92A, 970, 971	High Voltage Battery with Low SOC Disallows AC	9-12-17
<input type="checkbox"/>	8	8791	1801	Cayenne (92A)	A/C Evaporator Drains Clogging	7-20-18
<input type="checkbox"/>	9	9062	0202	Sports Cars (9x6)	Accessory Plug Fit Loose in Cigarette Lighter Socket	10-4-02
<input type="checkbox"/>	9	9112	0203	All	PCM Clock Skipping or Screen Going Dark	7-23-02
<input type="checkbox"/>	9	9687	0205	All	Check Fuse in Alarm Immobilizer Control unit	7-30-02

Literature Information

All  
1902

✓	Group	Part ID	Number	Model	Subject	Date
<input type="checkbox"/>	9	9112	0206	Sports Cars (9x6)	Obtaining PCM & Navigation Security Codes	7-30-02
<input type="checkbox"/>	9		0207	911 Turbo (996)	Fault Code - Airbag Connection	7-30-02
<input type="checkbox"/>	9	9144	0208	All	Bose Sound System Distortion	7-30-02
<input type="checkbox"/>	9	9120	0209	All	Becker 210 Radio Face Plate	7-30-02
<input type="checkbox"/>	9	9120	0212	All	Displaying Serial Number on Becker CDR220 & CR220	7-30-02
<input type="checkbox"/>	9	9662	0213	Sports Cars (9x6)	Emergency Entry to Vehicles With Lost Keys	9-13-02
<input type="checkbox"/>	9	9025	0215	All	Coding Instrument Clusters	12-6-02
<input type="checkbox"/>	9	9144	0220	All	Harmon Amplifier Popping and Crackling	12-13-02
<input type="checkbox"/>	9	9144	0301	All	Radio Has No Sound or Displays "Porsche"	2-14-03
<input type="checkbox"/>	9	9124	0403	Sports Cars	CDR23 Coding and Basic Troubleshooting	7-9-04
<input type="checkbox"/>	9	9100	0404	Cayenne (9PA)	Sound System Basic Troubleshooting	7-9-04
<input type="checkbox"/>	9		0501	Sports Cars (9x7)	Replacement Control Units	1-14-05
<input type="checkbox"/>	9		0502	Boxster (987)	Comfort Systems Rear Control Unit Coding Faults	1-13-05
<input type="checkbox"/>	9	9264	0504	Cayenne (9PA)	Rear Washer Nozzle Becomes Clogged	3-17-05
<input type="checkbox"/>	9	9662	0505	Sports Cars (9x6)	Remote Range is Poor or Intermittent	5-9-05
<input type="checkbox"/>	9	9110/9124	0506	Cayenne (9PA)	Radio/PCM Has Display But No Sound	5-23-05
<input type="checkbox"/>	9	9110/9124	0507	Sports Cars (9x6)	Radio/PCM Has Display But No Sound	5-23-05
<input type="checkbox"/>	9	9025	0508	Cayenne (9PA)	Service Interval Light Comes On Prematurely	5-23-05
<input type="checkbox"/>	9	9449	0509	Sports Cars (9x7)	"Warning Visit Workshop" in Instrument Cluster Cd. 8043	10-24-05
<input type="checkbox"/>	9	9449	0510	Sports Cars (9x7)	Fault C127-Front End Control Module Stored Code 8042	6-17-05
<input type="checkbox"/>	9	9112	0511	Sports Cars (9x7)	Overheating Fault in PCM Display	7-14-05
<input type="checkbox"/>	9	9112	0512	Cayenne (9PA)	Overheating Fault in PCM Display	7-14-05
<input type="checkbox"/>	9	9110	0513	Cayenne (9PA)	Additional Coding Information For PCM2.1	9-7-05
<input type="checkbox"/>	9		0515	Cayenne (9PA)	Miscellaneous Lamp Warnings In The Instrument Cluster	9-14-05
<input type="checkbox"/>	9	9110/9124	0601	All	PI Codes On CDR 23/24 & PCM 2.0/2.1	6-1-06
<input type="checkbox"/>	9	9666	0602	Cayenne (9PA)	KESY Control Unit Fault (0183) - Internal Antenna	6-16-06
<input type="checkbox"/>	9		0702	Cayenne (9PA)	W719 Workshop Campaign Listed in WWS Program HDLT	6-14-07
<input type="checkbox"/>	9	9110	0703	All	PCM/Infotainment Overview For Vehicles With PCM/CDR	7-27-07
<input type="checkbox"/>	9	W738	0705	Cayenne (9PA)	Workshop Campaign W738 Important Information	9-4-07
<input type="checkbox"/>	9		0706	Cayenne (9PA)	ParkAssistant and Accessory License Plate Frames	8-29-07
<input type="checkbox"/>	9	9665	0707	Cayenne (9PA)	Initial Charging & Current Draw of the Alarm Siren	12-5-07
<input type="checkbox"/>	9	9752	0801	Sports Cars (997)	Battery Drain Due to Starter Harness Damage	1-30-08
<input type="checkbox"/>	9		0803	Cayenne (9PA) & 9x7	Satellite Radio Control Unit	5-22-08
<input type="checkbox"/>	9		0804	Sports Cars (9x7)	No Messages/Incorrect Messages in Instrument Cluster	7-10-08
<input type="checkbox"/>	9		0805	Cayenne (9PA)	No Messages/Incorrect Messages in Instrument Cluster	7-10-08
<input type="checkbox"/>	9	9110/9124	0806	Sports Cars (9x7)	Surround Sound Fading Out In Rear Speakers W/Bose	8-8-08
<input type="checkbox"/>	9	9110/9124	0807	Cayenne (9PA)	Surround Sound Fading Out In Rear Speakers W/Bose	8-8-08
<input type="checkbox"/>	9		0809	911 (997)	VAL + PDK: Fault Entry "C151" in Various Control Units	12-8--08
<input type="checkbox"/>	9		0810	Sports Cars (9x7)	CDR 24 Has no Sound After Full Control Unit Search	12-15-08
<input type="checkbox"/>	9	9110	0901	Sports Cars (9x7)	Additional Coding Information For PCM2.1	3-2-09
<input type="checkbox"/>	9		0902	Sports Cars (9x7)	CDR 24 Displays "Protect"	3-2-09
<input type="checkbox"/>	9	6968/6953	0905	Cayenne (9PA)	Airbag Warning Light On In Cluster Fault Code 2511	7-2-09

✓	Group	Part ID	Number	Model	Subject	Date
<input type="checkbox"/>	9	9665	0907	Cayenne (9PA)	Alarm Siren Sounds Intermittently When Locking Vehicle	10-22-09
<input type="checkbox"/>	9	9662	0908	Panamera	KESY and Non-KESY Remote Issues	2-5-10
<input type="checkbox"/>	9	9662	1001	Panamera	KESY and Non-KESY Remote Issues - Band Pass Filter	2-5-10
<input type="checkbox"/>	9		1002	Panamera	External Power Supply Connections	6-22-10
<input type="checkbox"/>	9	9784	1003	Sports Cars (9x7)	Incorrect Labeling of Alarm Horn and 2 Tone Fuses	3-25-10
<input type="checkbox"/>	9	9746	1005	911 (997)	Battery Drain Due To Starter Harness Damage	4-30-10
<input type="checkbox"/>	9		1007	Cayenne (92A)	External Power Supply Connections	6-22-10
<input type="checkbox"/>	9	9752	1008	Panamera	Engine Ground Splice	7-20-10
<input type="checkbox"/>	9	9035	1011	Panamera	Restoring The Gateway Functionality After Aborting Pro.	10-4-10
<input type="checkbox"/>	9	9xxx	1014	Cayenne (9PA) & 9x7	CDR 30 Issues & Software Update CD - Loss of Data	11-11-10
<input type="checkbox"/>	9		1102	All	Relays, Replacement After Removal of Cover	5-16-11
<input type="checkbox"/>	9	9627	1104	Panamera & Cayenne (92A)	Compressor Run-in Functions	7-7-11
<input type="checkbox"/>	9		1105	Panamera & Cayenne (92A)	Learning Door Handle Antenna Parameters	7-15-11
<input type="checkbox"/>	9	9xxx	1106	Panamera & Cayenne (92A)	Local Interconnect Network Bus Diagnostics	8-16-11
<input type="checkbox"/>	9	9110	1108	Panamera	Change of Universal Audio Interface - iPod Connector	1-13-12
<input type="checkbox"/>	9		1201	Panamera	Missing or Incomplete VINs	8-29-12
<input type="checkbox"/>	9	9138	1204	Sports Cars (9x1)	XM Radio Antenna Amplifier Failures Due to ESD Damage	8-14-18
<input type="checkbox"/>	9	9xxx	1205	Sports Cars (9x7)	Coding 9x7 Vehicles For Auto Lock at 5 mph	12-19-12
<input type="checkbox"/>	9		1301	Cayenne (9PA)	Buzzing Noise From Speakers in Vehicles W/ASK System	4-5-13
<input type="checkbox"/>	9	9666	1302	Cayenne (9PA)	KESY Immobilizer Repairs	4-30-13
<input type="checkbox"/>	9	1726/9752	1306	All	Oil Ingress Into Engine Wiring Harness	6-28-18
<input type="checkbox"/>	9	9415	1307	Sports Cars (9x1)	Removing & Installing Headlights	12-10-13
<input type="checkbox"/>	9	9709	1403	Cayenne (9PA)	Wire Harness Corrosion in Driver's Footwell - No Start	7-23-14
<input type="checkbox"/>	9	9227	1404	All	Windshield Wiper Noise	7-30-14
<input type="checkbox"/>	9	9110	1404	All	PCM3.0 and PCM3.1 Overview	7-30-14
<input type="checkbox"/>	9	9227	1405	Macan	Phantom Swipe of the Windshield Wiper	10-3-14
<input type="checkbox"/>	9	9110	1502	All	FM/AM Radio Interference	6-9-15
<input type="checkbox"/>	9	9110	1504	All	SiriusXM Source Not Available in PCM	8-27-15
<input type="checkbox"/>	9	9470	1506	918 Spyder	Removal of the Additional Brake Light	11-20-15
<input type="checkbox"/>	9	9110	1507	All	Customer Complaint of Rear Camera Distortion	11-23-15
<input type="checkbox"/>	9	9478	1508	Panamera (970)	Headlight Beam Adjustment Def. Warning Message	3-23-16
<input type="checkbox"/>	9	9144	1509	All	Bose & Burmester Amplifiers Produce Noise	12-18-15
<input type="checkbox"/>	9	9170	1601	92A, 970 & 95B	Lane Change Assist Warning	1-5-16
<input type="checkbox"/>	9	9025	1602	Macan (95B)	Ambient Temperature Reading Slow to Update	1-15-16
<input type="checkbox"/>	9	9415/9431	1603	All	Moisture in Light Housings	2-9-16
<input type="checkbox"/>	9	9431	1604	Boxster/Cayman (981)	Excessive Condensation Inside Tail Lights	1-29-16
<input type="checkbox"/>	9	9415	1605	Macan (95B)	Headlamp Moisture	2-9-16
<input type="checkbox"/>	9	9436	1606	911 GT3 (991)	Abnormal Driving Behavior w/P0571	4-8-16
<input type="checkbox"/>	9	9179	1607	Macan (95B)	Voice Control Is Not Functional	4-29-16
<input type="checkbox"/>	9	9023	1608	Panamera (970)	Fuel Gauge Errantly Reads Full	5-5-26
<input type="checkbox"/>	9	9662	1609	All	Characteristics Of Remote Locking	5-5-16
<input type="checkbox"/>	9	9110	1611	All	PCM3.1 Rebooting in MY 2010-16 Vehicles	5-16-16



Literature Information

All  
1902

✓	Group	Part ID	Number	Model	Subject	Date
<input type="checkbox"/>	9	9110	1612	Macan (95B)	Apple CarPlay Not Functional On Vehicles w/PRSE	6-1-16
<input type="checkbox"/>	9	6963	1613	911 (991)	Airbag Control Unit	6-21-16
<input type="checkbox"/>	9	9940	1614	911, Macan, 718	AT&T Data Services Require Activation	6-29-16
<input type="checkbox"/>	9	9168	1615	Macan (95B)	Temperature Sensor Does Not Communicate	8-23-16
<input type="checkbox"/>	9	9152	1616	Cayenne Platinum (92A)	Initial Activation of Connect Services Fails	9-26-16
<input type="checkbox"/>	9	9627	1617	Macan (95B)	MIL, CAN Faults, and Loss of HVAC Control	11-7-16
<input type="checkbox"/>	9	9627	1619	970/9x1/9x2/92A/95B	Replacing A/C Switch Console	11-11-16
<input type="checkbox"/>	9	9666	1701	Sports Cars	"Double Beep" When Locking Doors After Pro.	1-17-17
<input type="checkbox"/>	9	9944	1702	Panamera (971)	Porsche Car Connect Initialization Fails	1-25-18
<input type="checkbox"/>	9	9940	1703	All MY 2017	Porsche Connect Registration Process	5-12-17
<input type="checkbox"/>	9	9940	1704	All w/PCM4.0/01	Porsche Car Connect & AT & T Customer Portals	6-8-17
<input type="checkbox"/>	9	9940	1705	All w/PCM4.x	Porsche Connect T-Mobile Issues	6-16-17
<input type="checkbox"/>	9	9025	1706	Macan (95B)	Programming/Coding of the Instrument Cluster	9-21-17
<input type="checkbox"/>	9	9035	1707	9x1, 982	Battery Maintainer is Ineffective When Vehicle Sleeps	9-26-17
<input type="checkbox"/>	9	9025	1708	Panamera (971)	Instrument Cluster TFT Displays Inactive	10-20-17
<input type="checkbox"/>	9	9025	1709	Panamera (971)	Faulty Instrument Cluster Disallows Cruise Control	10-20-17
<input type="checkbox"/>	9	9787	1710	Panamera (971)	Ground Strap Loose or Coated, Causes Starter Issues	11-8-17
<input type="checkbox"/>	9	9025	1711	All 1997-on	Setting Total Distance in the Instrument Cluster	12-21-17
<input type="checkbox"/>	9	9035	1801	Panamera (971)	Programming Failures Due to Gateway Control	1-17-18
<input type="checkbox"/>	9	9110	1802	All (MY2009-16	Enabling Individual Memory on PCM3.0/3.1	1-17-18
<input type="checkbox"/>	9	9152	1803	Panamera (971)	Do Not Update MY17 PCM4.1 Software	1-25-18
<input type="checkbox"/>	9	9662	1804	Panamera (971)	Remote Key Batteries Are Prematurely Dead	2-26-18
<input type="checkbox"/>	9	9942N	1806	Panamera (971)	Apple CarPlay Interrupted After Reverse Camera Engages	4-10-18
<input type="checkbox"/>	9	9662C	1807	Panamera (971)	Remote Key Batteries Are Prematurely Discharged	9-26-18
<input type="checkbox"/>	9	9138S	1808	Sports Cars (982/991)	SDARS Antenna Faulty, Disassembly Before Painting	8-14-18
<input type="checkbox"/>	9	9063	1809	911 GT3 (991)	False E-Call Caused by Faulty Airbag Module	8-17-18
<input type="checkbox"/>	9	9679	1810	Panamera (971)	MyQ Garage Door/Gate Opener Loses Programming	9-17-18
<input type="checkbox"/>	9	9431	1811	Cayenne (9YA)	Small Cracks Edge of Tail Lights	10-26-18
<input type="checkbox"/>	9	9196	1812	Cayenne (9YA)	Flight Mode Deactivation Fails Communication Check	10-26-18
<input type="checkbox"/>	9	91520	1813	Cayenne (9YA)	Mobile Data Module Resets and Disallows Data Connection	11-6-18
<input type="checkbox"/>	9	9128	1814	971, 9YA	Panamera & Cayenne Coaxial Cable Ordering Concept	11-16-18
<input type="checkbox"/>	9	9662	1815	Panamera (971)	Replacement Keys Disallow KESSY Function	12-12-18
<input type="checkbox"/>	9	9431	1816	Cayenne (92A)	Tail Light Defective Warning in Instrument Cluster	12-13-18
<input type="checkbox"/>	9	9241	1901	Cayenne (9YA)	Rear Wiper Arm Cover Falls Off	2-1-19
<input type="checkbox"/>	9	9035	1902	Cayenne (9YA)	No Start/No T15 Response Corrected by Con Box	2-14-19
<input type="checkbox"/>	<b>9</b>	<b>91500</b>	<b>1903</b>	<b>95B, 982, 991, 92a</b>	<b>Inconsistent, Unpredictable Feedback Beeps</b>	<b>4-26-19</b>
<input type="checkbox"/>	<b>9</b>	<b>9679</b>	<b>1805</b>	<b>Panamera (971)</b>	<b>Homelink Will Not Program</b>	<b>8-29-19</b>
<input type="checkbox"/>	<b>9</b>	<b>91203</b>	<b>1905</b>	<b>Macan (95B)</b>	<b>Difficulty Installing Onboard Owner's Manual into PCM</b>	<b>9-23-19</b>
<input type="checkbox"/>	X		0201	All	Special Gun Metal Paint For Sport Interiors	7-30-02
<input type="checkbox"/>	X		0602	All	Control Unit & Special Tool Rental Procedures	8-8-05
<input type="checkbox"/>	X		0800	All	Correct Way to Handle Sealing Rings After Removal	5-14-08
<input type="checkbox"/>	X		0801	All PTEC Users	PTEC Priority Level Descriptions	7-23-08