





MPD UPDATE


Electrical



No Start Due to GWM		19MY – 20MY RR Velar	
<p><u>Problem Description:</u></p> <ul style="list-style-type: none"> - Customer is able to unlock and lock the vehicle but not able to start vehicle. <p><u>Current Status:</u></p> <ul style="list-style-type: none"> - UK Engineering working with supplier to address this concern. <p><u>Recommended Actions:</u></p> <ul style="list-style-type: none"> - Please submit an EPQR if you encounter this scenario as parts need to be returned for analysis. 			
KPI's			
Total VIN Count	Status	Issue Owner	
		NAS: Richard Conte	

 Solution Unavailable or project not yet accepted

 Solution known, not yet delivered

 Service Fix Available, Communication Published

