

MPD UPDATE

Powertrain



Diesel Particulate Filter (DPF) Efficiency DTC P2002-00		17-19MY 3.0L TDV6 Equipped Vehicles
<p><u>Problem Description:</u></p> <ul style="list-style-type: none"> - Check Engine lamp illuminated with DTC P2002-00 stored in the PCM which requires DPF replacement <p><u>Current Status:</u></p> <ul style="list-style-type: none"> - Software is now available on Pathfinder from 17 & 18MY Vehicles- with 19MY calibration in development with expected availability in 6 weeks <p><u>Recommended Actions:</u></p> <ul style="list-style-type: none"> - Should a vehicle have P2002 stored in the PCM, replace the DPF and update the PCM to the latest level with the current version of PATHFINDER. Once P2002 is stored, the DPF cannot be recovered and needs to be replaced. The PCM update prevents future occurrences of P2002. 		
KPI's		
Total VIN Count	Status	Issue Owner
		Elyse McArthur

Solution Unavailable or project not yet accepted

Solution known, not yet delivered

Service Fix Available, Communication Published

