

## GPOP - Issue Review System

**Part Number:** 68159667A\$, 68159666A\$

**Part Description:** SHAFT, Axle Half, Left/Right

**Issue Description:** If you are working on a Ram ProMaster with a Noisy, Leaking, or Damaged Front Halfshaft/CV Boot, please take a picture of the damage on shaft, ideally prior to removal, and contact Dennis Battle at (734) 231-1540 to have the part returned to FCA via FasTrack.

If no response in 15 minutes, proceed with repair.

~  
Contact us at [CAGRIS@Chrysler.com](mailto:CAGRIS@Chrysler.com) for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.  
~