

GPOP - Issue Review System

Part Number: L0007444N\$

Part Description: LAMP, Park and Turn Signal

Issue Description: For concern of turn signal bulb inoperative/broken or blown, please replace the entire lamp assembly (55112720A\$ or 55112721A\$) instead of replacing the affected turn signal bulb.

Please call Jonathan Atanasio Gil at (+52) 1 722-419 48 59 or at Alan Leon (248) 245-8049 prior to replacing the component (if needed).

If no response in 15 minutes, proceed with repair.

~____~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
