

## GPOP - Issue Review System

**Part Number:** 68395010A\$, 68234994A\$, 68055262A\$

**Part Description:** Transfer case seal, Transmission Output Seal

**Issue Description:** If vehicle has a fluid leak between the transfer case and the transmission on an AWD vehicle and it has been determined that the transfer case is leaking from the vent hole, don't replace the input seal. The vehicle can be repaired by:

Transfer Case replace -  
68214750A\$ 3.6 Pentastar  
68214751A\$ 5.7 Hemi

Replace Front Case Half -  
68101734A\$ 3.6 Pentastar  
68101734A\$ 5.7 Hemi

Note: The transfer case oil already has dye in it so leak confirmation with a black light can be achieved.

~ \_\_\_\_\_ ~  
Contact us at [CAGRIS@Chrysler.com](mailto:CAGRIS@Chrysler.com) for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.

---