

## **GPOP - Issue Review System**

**Part Number:** 68204730A\$, 68041137A\$, 04877128A\$

**Part Description:** Air Suspension Components

**Issue Description:** Star Parts Catalog has been updated to show individual service parts for the compressor assembly. This will allow service technicians to repair the root cause without over repairing the system. Replace only the part deemed failed by the diagnostics performed.

Individual parts include:

- Compressor
- Valve block
- Individual hoses
- Temp sensor
- Shield
- Air line clips

NOTE: in most situations when a new compressor is needed, the compressor as a separate part is the correct repair, and the assembly would not be required.

~  
Contact us at [CAGRIS@chrysler.com](mailto:CAGRIS@chrysler.com) for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.  
~