

GPOP - Issue Review System

Part Number: 68089468A\$

Part Description: BLOCK, Fuse

Issue Description: For concern of damaged fuse block, please also replace the jump start wiring harness (68322414A\$) and contact David Petrow at (248) 884-9206 or david.petrow@fcagroup.com, to set up FasTrak of these components to QEC for further analysis.

If no response in 15 minutes, proceed with repair.

~_____
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.