

Subject: **Engineering Information – Melted Stone Guard On the Right Rear Quarter Panel From Exhaust Heat and/or Making Contact with the Exhaust Tip**

This PI has been revised to end the need for information from the field. Please discard PIE0531.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado 1500 (New Model)	2019	2019	-	-	Equipped with 2.7L Engine (RPO L3B)	-
GMC	Sierra 1500 (New Model)						

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	2
Modified	Released August 19, 2019 Revised December 04, 2019 – Ended the need for further information from the field.