



Technical Bulletin 203
12.2019

Contents


Item	Subject	Model Affected
203.1	Rear Bevel Box Breather	Rocket 3 GT, Rocket 3 R, Rocket 3 TFC

Item: 203.1
 Description: Rear Bevel Box Breather
 Model Affected: Rocket 3 GT, Rocket 3 R, Rocket 3 TFC

! Caution

Do not use high pressure spray washers or steam cleaners.
 Use of high pressure spray washers and steam cleaners may damage seals, cause water and steam to be forced into bearings and other components causing premature wear from corrosion and loss of lubrication.

For the above models from VIN 971688 the rear bevel box is fitted with a breather.
 Before washing the motorcycle make sure the engine and the rear bevel box are cold.
 While washing the motorcycle care must be taken when cleaning the rear bevel box to make sure water does not enter the breather.



- 1. Breather
- 2. Bevel box

Dealers are requested to inform the owners of this information when they collect their motorcycle.

Circulation

Initial and date when read and return to central file holder

Service Manager	Parts Manager	Sales Manager	Workshop Supervisor	Technician 1	Technician 2