

Subject HVAC Evaporator Cleaning Service Tips		Market USA
Service Category Vehicle Interior	Section Heating/Air Conditioning	
Applicability 2018-2020 C-HR		

APPLICABLE VEHICLES

2018-2020	C-HR
-----------	------

CONDITION

On 2018-2020 model year C-HR vehicles follow the recommendations when performing the HVAC odor maintenance service using A/C Power Foam Evaporator Cleaner & Refresher.

RECOMMENDATIONS

Cover the area under the HVAC unit – Perform this step before HVAC evaporator cleaning process is started.

1. Remove the trim components under the HVAC unit.
 - [Remove Front No.2 Console Box Insert \(RM Step #8\).](#)

2. Cover the area under the HVAC unit and its surroundings.
Hint: Recommend Industrial Absorbent Pads to cover.



3. Perform the HVAC odor maintenance service using Toyota Genuine A/C Refresher Kit.
4. After performing HVAC odor maintenance service, wait 30 minutes before removing absorbent material and reassembling the trim panels.

LINK REFERENCES

- [Link References of HVAC Evaporator Cleaning Process\(Youtube Video\)](#)