

Subject		Market	
HVAC Evaporator Cleaning Service Tips		USA	
Service Category	Section		
Vehicle Interior	Supplemental Restraint Systems		
Applicability			
2019-2020 UX200, 2019-2020 UX 250H			

APPLICABLE VEHICLES

2019-2020	UX250H	2019-2020	UX200
-----------	--------	-----------	-------

CONDITION

On 2019-2020 model year UX200 and 2019-2020 model year UX250H vehicles follow the recommendations when performing the HVAC odor maintenance service using A/C Power Foam Evaporator Cleaner & Refresher.

RECOMMENDATIONS

Cover the area under the HVAC unit – Perform this step before HVAC evaporator cleaning process is started.

1. Remove the trim components under the HVAC unit.
 - [Remove Front No.2 Console Box Insert \(RM Step #25\)](#).
2. Cover the area under the HVAC unit and its surroundings.

Hint: Recommend Industrial Absorbent Pads to cover.
3. Perform the HVAC odor maintenance service using Toyota Genuine A/C Refresher Kit.
4. After performing HVAC odor maintenance service, wait 30 minutes before removing absorbent material and reassembling the trim panels.

LINK REFERENCES

- [Link References of HVAC Evaporator Cleaning Process\(Youtube Video\)](#)