


PARTS HOTWIRE

Millimeter Wave Radar Sensor

SSC KOB, Certain 2018-2019 MY Tacoma & Tundra



Certain millimeter wave radar sensor part numbers have been placed on MAC. These parts have been placed on MAC to help ensure that the sensor has the correct software version and that sealer has been applied prior to installation on a vehicle. The following part numbers have been placed on MAC.

Part Number	Applicability
88210-04010	Tacoma
88210-04020	Tacoma TRD
88210-0C010	Tundra
88210-0C030	Tundra TRD

- These parts will **ONLY** be released to vehicles that do not have campaign KOB completed until further notice.
- Based on the inspection results in the KOB technical instructions, the millimeter wave radar sensor may require replacement.
- Parts should **ONLY** be ordered, when completing KOB, if the diagnosis following the technical instructions/repair manual determines sensor replacement is required.

For release of a millimeter wave radar sensor by PTSG (Parts Technical Support Group), you will be required to email PRaproject@toyota.com the following:

- ✓ VIN
- ✓ Part Number and Quantity
- ✓ Dealer Number
- ✓ Order Reference Number
- ✓ Contact Name and Number
- ✓ **Screenshot of Diagnostic Trouble Code(s) (DTC) resulting in the need to replace the sensor**
- ✓ **If replacement is not related to a DTC, an explanation of why the part is needed (ex: collision damage)**

Release requirements can be found in the latest MAC Report. Also, please refer to the Dealer Letter and Technical Instructions on TIS for additional SSC information.

