

GPOP - Issue Review System

Part Number: 2AMV8043A\$

Part Description: ROTOR, Brake, Rear

Issue Description: Counter bore hole on the original rotor is used during production to locate the rotor during assembly, it is not required for service.

2AMV8043A\$ can be used for this application.

~____~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
