



Technical Journal

TITLE:

DIM message about parking brake

REF NO: TJ 34647.1.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7510 Volvo Car USA		ISSUE DATE: 2019-09-13	STATUS DATE: 2019-09-17
FUNC GROUP: 5930	FUNC DESC: Anti-lock brake (anti-skid)	Page 1 of 2	

“Right first time in Time”

Attachment

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
234							2016-2018		0000350-0045786	201617-201816
235							2017-2018		0000160-0070025	201624-201816
236							2017-2018		0000098-0038262	201646-201816
238							2017-2018		0000161-0057375	201646-201816
246							2017-2018		0000389-0125697	201717-201816
256							2016-2018		0000561-0391758	201505-201816

CSC Customer Symptom Codes

Code	Description
IV	Text window and warning symbol/Text message
PK	Parking brake/No/reduced/incorrect function

VST Operation Number

VST Operation Number	Description
36002-3	Software control module downloading (2:nd download)
36004-2	Software control module downloading



DTC Diagnostic Trouble Codes

Control Module	Code	Fault Type
BCM	B111177	Intermittent
BCM	B111167	Intermittent
SRS	U2C8692	Intermittent

Text

DESCRIPTION:

If the DIM message “Parking brake not fully released” or “Auto Hold service required” is present in combination with any of the DTC’s, please follow instructions under “Service”.

SERVICE:

1. Verify the symptom and DTC’s.
2. Perform a software upgrade in accordance with TJ 31543.
3. Download software product for applicable vehicle type.

32267723 - S90, V90, V90CC

31493654 - S90L

32267751 - XC90, XC60

This journal will be updated when the permanent solution is available.

Warranty claim info:

These special software, SP: 32267723, 31493654, 32267751, is “free of charge” and will not create any invoice. The special software can therefore not be claimed as a warranty cost.

To get warranty claim accepted for the labor part described in this TJ, please use following data:

VST OP number: 36004-2 and 36002-3 and relevant CSC.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area “Vehicle Report” and sub concern area “Support Needed”, use function group 5930.