

# PRODUCT INVESTIGATION POWERTRAIN

CAPABLE  
OF GREAT  
THINGS  
PALM SPRINGS 2020

Engine Speed Instability at low RPM	19/20 MY Range Rover and RR Sport equipped with AJ20P6
<p><b><u>Customer Voice:</u></b></p> <ul style="list-style-type: none"><li>• The engine runs rough at idle.</li><li>• The vehicle stalled, the vehicle could be restarted on the next ignition cycle.</li></ul> <p><b><u>Technical Description:</u></b></p> <ul style="list-style-type: none"><li>• The condition may be experienced at various speeds with low engine RPM.</li><li>• The vehicle can be restarted on the next ignition cycle.</li></ul> <p><b><u>Status:</u></b></p> <ul style="list-style-type: none"><li>• A revised PCM and TCM calibration is available in PF261 to address this condition.</li><li>• Perform a thorough road test after the programming to allow for adaption values to set.</li><li>• UPS N407 launched December 5<sup>th</sup> 2019</li></ul>	