

SS 1034179 - WST Speedo Errors

WST Speedo Errors

Applicable Vehicles

All WST Model with the exception of 5700s

Symptoms

See Below

Speedo Concerns and Fixes

Speedo dropping out altogether

- The part numbers affected were: A22-71439-xxx, A22-71437-xxx and A22-71438-xxx. Replace gauges with part numbers A22-76315-xxx.

Speedo odometers resetting back to zero

- There is a module inside the speedo that records the mileage. It was replaced to correct this issue. Use part numbers A22-76315-xxx gauges to replace faulty gauges.