

AWNING DOES NOT EXTEND PROPERLY. Awning sticks on aft side, cause unknown. Manually pull out aft side of awning while assistant activates via touch screen. Found catch and lock mechanism appears warped in manufacture. Carefully file down to provide proper clearance and apply dry lubricant. Test operation multiple times.