



Service Bulletin

Bulletin No.: 20-NA-006

Date: January, 2020

INFORMATION

Subject: Information on Cold Weather Steering Hose Upgrade Kit

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado 2500HD/ 3500HD	2015	2020				
GMC	Sierra 2500HD/ 3500HD	2015	2020				

Involved Region or Country	North America
Condition	Some customers may comment on a power steering leak from the power steering hoses.
Cause	This condition may be caused by extreme cold affecting the pliability of the power steering hoses.
Correction	<p>Note: Some dealers may not be aware of the Cold Weather Steering Hose Upgrade Kit. Replace the power steering hose with a Cold Weather Steering Hose Upgrade Kit available from the GM Accessory Group.</p> <p>Important: The power steering hose upgrade kit replacement is a vehicle option and should only take place after a customer agreement for payment is obtained.</p> <p>⇒ Refer to Parts Information section below for ordering information.</p>

Parts Information

https://aic.gm.com/cms/home/tools/accessory-portfolio-search.html
https://ca-aic.autopartners.net/cms/home.html (Canada)

Version	1
Modified	Released January 14, 2020