



Condition

ATTENTION:**THIS IS A TECH TIP, NOT A TECHNICAL BULLETIN.****TECH TIPS ARE NOT ASSOCIATED WITH WARRANTY CLAIMING.**

Applicable Vehicles

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Beetle, Beetle Convertible, Tiguan LWB, Passat	2018-2019	2.0L (DDSA, DGUA)	All	All	All

Revision Table

Instance Number	Published Date	Version Number	Reason For Update
2058719/1	2/21/2020	01-20-02TT	Original publication.

Technical Background

Injector circuit faults, which may present intermittently, in the -**J623**- Engine/Motor Control Module.

DTC	Description
P0201	Cylinder 1-Injector Circuit
P0202	Cylinder 2-Injector Circuit
P0203	Cylinder 3-Injector Circuit
P0204	Cylinder 4-Injector Circuit

Production Solution

NA.

Service

If the above DTC's are present in the ECM:

- Replace the T8 fuel injector harness.



Additional Information

© 2020 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.