



Modify Air Dryer TCOV

Description:

120 trucks be built with 21255207 w/ TCOV and equipped with 2COMP900 – the TCOV will cause premature wear to unloader valve in compressor due to back pressure kept in the discharge line.

Corrective Action:

Remove Turbo Cut Off Valve assembly from air dryer. Disassemble Turbo Cut Off Valve. Remove internal spring in Turbo Cut Off Valve Assembly. Reassemble Turbo Cut Off Valve Assembly and reinstall on air dryer. (see attached photo/diagram)

UCHP SCC CODE: S7454

EXPIRATION DATE: 2/28/2021

CAUSAL PART NUMBER: 21255207

UCHP Labor Code:

5618-03-02-06 – Air Dryer Valve, Replacement – 0.4

PARTS MARKUP: 30%

PARTS LIST:

None Required

FOR MORE INFORMATION CONTACT: Michael Moriarty

michael.moriarty@volvo.com

Air Dryer Turbo Cut-Off Valve Deactivation

Campaign Instructions

