

FOUND DURING PRE DELIVERY INSPECTION AWNING UNEVEN. Held awning up and adjusted awning by tightening bolts, did multiple times as awning would not level, tested and works proper.