

GPOP - Issue Review System

Part Number: 68426872A\$, 68426873A\$, 68426877A\$

Part Description: HEADLAMP

Issue Description: After performing the headlamp condensation clearing service procedure, If the WK Headlamp is being replaced for Moisture / Condensation issue, please e-mail pictures of the Moisture / Condensation issue to FCA Redacted Content and then continue with the replacement.

~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
~
