

## **GPOP - Issue Review System**

**Part Number:** 68290764A\$

**Part Description:** SWITCH, Power Window

---

**Issue Description:** For concern of rear windows INOP from the rear window switch, please contact FCA Redacted Content before replacing the part.

If no response in 15 minutes, proceed with repair.

~\_\_\_\_\_  
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.

---