



Heated Seat Temperature Lower Than Expected	18 -20MY Range Rover, RR Sport, 20MY RR Evoque, Discovery, Discovery Sport
<p>Customer Voice:</p> <ul style="list-style-type: none">• A customer may report that the heated seats are slow to warm or cool off. <p>Technical Description:</p> <ul style="list-style-type: none">• A potential HVAC software concern has been identified on specific 18-20MY vehicles where the heated seats are either temperature is slow to increase when turned on or temperature is slow to decrease when turned off.• This applies to heated only seats, seats with the heat/ cool feature are not affected by this concern. <p>Status:</p> <ul style="list-style-type: none">• A revised HVAC software has been developed and released on PATHFINDER 274 to address this concern.• TSB JLRTB0214NAS2 is being published to address this concern on.	

