

GPOP - Issue Review System

Part Number: 6TX43BD3A\$, 6TX43LA8A\$, 6XA70BD3A\$, 6RE67BD3A\$, 6XA71BD3A\$,
6RE59BD3A\$, 6RE32BD3A\$, 6RE66BD3A\$, 6RE39BD3A\$, 6RE39LR5A\$,
6RE46BD3A\$, 6RE55LT5A\$

Part Description: COVER, Front Seat Cushion

Issue Description: For a seat cover that is loose at the seat frame attachment clips, please perform TSB 23-025-19

Seat cover replacement is not required

~_____
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.