

GPOP - Issue Review System

Part Number: 68164107A\$

Part Description: SWITCH, Fuel Door

Issue Description: For concern of fuel door button inoperative, FCA engineering is requesting the fuel door button along with the driver kneeblocker panel assembly be returned to FCA through the normal part return process in an undisturbed state (do not attempt to remove fuel door button). The kneeblocker panel service part numbers are as follows:

5SA98DX9AB - Knee blocker panel

5SA98HL1AB - Knee blocker panel

In addition, FCA would like to request that you document the VIN and provide the following information:

1.) Take image of customer concern (Front and back of assembly) - Highlighting if fuel door button is stuck in the knee blocker panel

2.) Email images of concern to *FCA Redacted Content* and FCA Redacted Content

For additional questions, contact *FCA Redacted Content*. If no response in 15 minutes, proceed with repair.

~ ~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
