

**90-20-02TT Fuel Gauge Reads Empty after Fuel Sending Unit Replacement**

Condition

ATTENTION:**THIS IS A TECH TIP, NOT A TECHNICAL BULLETIN.****TECH TIPS ARE NOT ASSOCIATED WITH WARRANTY CLAIMING.****Applicable Vehicles**

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Touareg	2011-2017	All	All	All	All

Revision Table

Instance Number	Published Date	Version Number	Reason For Update
2059378/1	4/24/20	90-20-02TT	Original publication.

Technical Background

Fuel gauge reads empty after sending unit replacement.

Service

Perform a Capacitive Discharge.

- Disconnect the negative battery cable and then the positive cable.
- Connect the cables to each other for 1 minute.
- Assemble in reverse order.
- Restore electrical power and evaluate for any additional concern.

Additional Information

© 2020 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.