

2020 FIT G101 Inspection



Inspection Procedure :

1. With both engine and vehicle off, open the hood and locate ground terminal lug for G101.



2. Visually inspect the ground terminal (see next page for visual inspection criteria):
3. If a **NO GOOD** condition is found, take a photo to document your findings, then contact AHM TRS by sending the photo, VIN and your contact information to trs@ahm.honda.com for further instruction. **DO NOT ATTEMPT A REPAIR** until receiving further instruction from AHM TRS.
4. If **OK**, no further action is required. Please see the warranty information for the inspection on page 3.

2020 FIT G101 Inspection

| | Inspection Criteria | |
|------------------------------|--|--|
| Component | OK | NO GOOD |
| <p>G101 Terminal Lug</p> |  <ul style="list-style-type: none"> • Tape is securely wrapped around harness loom • Ground terminal lug secure and in place • Ground terminal lug is relatively straight • No visible crease(s) or bend(s) on ground lug terminal |  <ul style="list-style-type: none"> • Harness loom and tape pulled back • Ground terminal lug broken at crimp <ul style="list-style-type: none"> - and/or - • Visible crease(s) or bend(s) on ground lug terminal |

2020 FIT G101 Inspection

Warranty Information:

Labor Operation Number: 7100A0

Flat-Rate Time: 0.2 hr.

Defect Code: 09999

Symptom Code: 03217

Failed P/N: 32110-5R1-A14 / WIRE HARNESS, ENGINE