



Subject		Market
<b>Rear Whine Noise While Driving at Highway Speeds</b>		USA
Service Category	Section	
Drivetrain	Transfer/4wd/Awd	
Applicability		
2019-2020 UX250H		

**APPLICABLE VEHICLES**

2019-2020	UX250H
-----------	--------

**CONDITION**

Some 2019-2020 model year UX250h vehicle may experience a whine/humming noise at 70-80 mph from the rear of the vehicle. This condition can occur on vehicles with less than 10,000 miles.

**RECOMMENDATIONS**

This is currently under investigation and not a normal characteristic of the vehicle.

Please create a TAS case and contact TAS for instruction prior to diagnosing or repairing of the vehicle. If it is a weekend or holiday, continue with diagnosis and repair. Please save all parts and/or details and contact TAS on the next available work day.

**LINK REFERENCES**

This Tech Tip does not contain any link references